

HUMMER H1							ENGINE						
OPERATION DESCRIPTION	OPERATION NUMBER	ENGINE					MODEL						
		X	Y	Z/F	D/L	P	82	83 and 56	84 and 57	85	89 and 55	90 and 58	91 and 59
SOME LABOR OPERATIONS IN THIS SECTION HAVE AN ADD CONDITION "TO CLEAN PARTS ON VEHICLES OVER 30,000 MILES IF NEC." WHEN CLAIMING THIS "ADD," THE PARTICULAR LABOR OPERATION INVOLVED MUST BE CITED AS Y-TIME (ADD TIME).													
ENGINE OIL LEAK-ANALYZE	b2000	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
INC: Add dye, run engine, inspect for leaks with black light.													
ENGINE ASSEMBLY-REPLACE	b2005	18.6	18.6	18.6	18.6	18.6	-	-	-	-	-	-	-
POLICY: A													
NOTE: Complete engine.													
ADD:													
A - With A/C		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
B - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
C - 2004 Model Year		-	-	1.5	-	-	-	-	-	-	-	-	-
ENGINE, UNIVERSAL (long block)-REPLACE	b2010	24	24	24	24	-	-	-	-	-	-	-	-
POLICY: A													
INC: Transfer of Nec. Parts													
NOTE: Remanufactured engine.													
ADD:													
A - With A/C		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
B - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
C - 2004 Model Year		-	-	1.5	-	-	-	-	-	-	-	-	-
BLOCK, ENGINE FITTED-REPLACE	b2015	30	30	30	30	-	-	-	-	-	-	-	-
POLICY: A													
ADD:													
A - With A/C		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
B - To Recondition All Valves		2.5	2.5	2.5	2.5	-	-	-	-	-	-	-	-

[illegible]

one cyl														
right bank	b2065	10	10	10	3.6	-	-	-	-	-	-	-	-	-
left bank	b2066	8.9	8.9	8.9	3.5	-	-	-	-	-	-	-	-	-
both banks	b2067	11.9	11.9	11.9	3.8	-	-	-	-	-	-	-	-	-
ADD:														
A - To Replace All Lifters (Each Side)		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
B - To Clean Parts On Vehicles Over 30,000 Miles If Necessary														
Right or Left		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-	-
Both		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
C - 1999 Model Year and Above, left bank and both banks		-	-	0.5	-	-	-	-	-	-	-	-	-	-
D - 2004 Model Year		-	-	1.5	-	-	-	-	-	-	-	-	-	-
GUIDE AND/OR CLAMP, LIFTER-REPLACE														
one cyl														
right bank	b2070	10	10	10	-	-	-	-	-	-	-	-	-	-
left bank	b2071	8.9	8.9	8.9	-	-	-	-	-	-	-	-	-	-
both banks	b2072	11.9	11.9	11.9	-	-	-	-	-	-	-	-	-	-
ADD:														
A - To Replace All Guides and/or Clamps														
Right or Left		0.1	0.1	0.1	-	-	-	-	-	-	-	-	-	-
Both		0.2	0.2	0.2	-	-	-	-	-	-	-	-	-	-
B - To Clean Parts On Vehicles Over 30,000 Miles If Necessary														
Right or Left		0.2	0.2	0.2	-	-	-	-	-	-	-	-	-	-
Both		0.3	0.3	0.3	-	-	-	-	-	-	-	-	-	-
C - 1999 Model Year and Above, left bank and both banks		-	-	0.5	-	-	-	-	-	-	-	-	-	-
D - 2004 Model Year		-	-	1.5	-	-	-	-	-	-	-	-	-	-
PULLEY, CRANKSHAFT-REPLACE	b2075	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-	-
ADD:														
A - With A/C		0.5	-	-	-	-	-	-	-	-	-	-	-	-
DAMPER, TORSIONAL-REPLACE	b2080	0.9	0.9	0.9	0.9	1.1	-	-	-	-	-	-	-	-

[illegible]

[illegible]

HARNESS, RELAYS TO GLOW PLUGS	b2250	0.5	0.5	0.6	-	-	-	-	-	-	-	-	-
(DIESEL)-REPLACE													
SOLENOID, FAST IDLE (DIESEL)-REPLACE	b2255	0.4	0.4	0.4	-	-	-	-	-	-	-	-	-
PLUGS, GLOW (DIESEL)-REPLACE													
side													
right one or more	b2261	0.7	0.7	0.7	-	-	-	-	-	-	-	-	-
left one or more	b2262	0.5	0.5	0.5	-	-	-	-	-	-	-	-	-
both one or more	b2263	1	1	1	-	-	-	-	-	-	-	-	-
Model year 2006		-	-	-	-	-	-	-	-	-	-	-	-
one	B2264	-	-	-	-	0.5	-	-	-	-	-	-	-
each additional	B2265	-	-	-	-	0.2	-	-	-	-	-	-	-
INC: Diagnosis													
ADD:													
A - If Damaged Or Broken Tip		0.6	0.6	0.6	-	-	-	-	-	-	-	-	-
B - 1999 Model Year and Above, Left Bank and Both		-	-	0.2	-	-	-	-	-	-	-	-	-
MODULE, GLOW PLUG CONTROL (DIESEL)-REPLACE													
POLICY: E													
INC: Diagnosis													
controller/relay	b2270	1.2	1.2	1.2	-	2	-	-	-	-	-	-	-
WIRES, SPARK PLUG-REPLACE													
INC: Diagnosis with oscilloscope or equivalent.													
right bank	b2275	-	-	-	1.6	-	-	-	-	-	-	-	-
left bank	B2276	-	-	-	1.6	-	-	-	-	-	-	-	-
both	B2277	-	-	-	2	-	-	-	-	-	-	-	-
PLUGS, SPARK-REPLACE													
INC: Diagnosis with oscilloscope or equivalent.													
one or two	b2280	-	-	-	0.5	-	-	-	-	-	-	-	-
all	b2281	-	-	-	1.8	-	-	-	-	-	-	-	-
COIL, DISTRIBUTOR-REPLACE	b2282	-	-	-	1.8	-	-	-	-	-	-	-	-

INC: Diagnosis with oscilloscope or equivalent.													
CAP, DISTRIBUTOR-REPLACE	b2283	-	-	-	1.8	-	-	-	-	-	-	-	-
INC: Diagnosis with oscilloscope or equivalent.													
ROTOR, DISTRIBUTOR-REPLACE	b2284	-	-	-	1.8	-	-	-	-	-	-	-	-
INC: Diagnosis with oscilloscope or equivalent.													
WIRE, DISTRIBUTOR TO COIL SECONDARY-REPLACE	b2285	-	-	-	1.6	-	-	-	-	-	-	-	-
INC: Diagnosis with oscilloscope or equivalent.													
SENSOR, ELECTRONIC SPARK CONTROL KNOCK-REPLACE	b2286	-	-	-	0.4	-	-	-	-	-	-	-	-
MODULE, DISTRIBUTOR-REPLACE	b2287	-	-	-	1.8	-	-	-	-	-	-	-	-
PICK-UP COIL AND/OR POLE PIECE, DISTRIBUTOR-REPLACE	b2290	-	-	-	3.3	-	-	-	-	-	-	-	-
INC: Diagnosis with oscilloscope or equivalent. R&R distributor, distributor gear and mainshaft assy. Align pick-up coil, check and adjust timing and idle speed as nec.													
MAINSHAFT, DISTRIBUTOR-REPLACE	b2295	-	-	-	3.1	-	-	-	-	-	-	-	-
INC: Adjust timing.													
DISTRIBUTOR ASSEMBLY-R&R OR REPLACE	b2300	-	-	-	2.7	-	-	-	-	-	-	-	-
INC: Adjust timing.													
ADD:													
A - To replace distributor Gear		-	-	-	0.1	-	-	-	-	-	-	-	-
B - To Recondition Complete		-	-	-	0.3	-	-	-	-	-	-	-	-
TIMING-ADJUST	b2305	-	-	-	1.5	-	-	-	-	-	-	-	-
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	b2310	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-

[illegible]

[illegible]

[illegible]

A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
SHIELD, EXHAUST CATALYTIC CONVERTER-REPLACE	c3456	0.4	0.4	1	0.6	0.4	-	-	-	-	-	-	-
PIPE, Exhaust Down - Replace	C3457	-	-	-	-	2.8	-	-	-	-	-	-	-
CONVERTER, EXHAUST CATALYTIC-REPLACE	c3461	-	1	1.8	1.8	1	-	-	-	-	-	-	-
POLICY: E													
PIPE, REAR EXHAUST-REPLACE (94 & 95 ONLY)	C3466	-	0.6	-	0.6	-	-	-	-	-	-	-	-
MUFFLER-REPLACE	C3471	1	0.6	0.6	0.6	-	-	-	-	-	-	-	-
PIPE, TAIL-REPLACE	C3481	0.4	0.6	0.6	-	0.6	-	-	-	-	-	-	-
INC: Replace hanger bracket if nec.													
NOTE: Include shield, attenuator or resonator.													
EXHAUST SYSTEM (COMPLETE)-REPLACE	c3482	3.7	4.5	4.5	3	4.5	-	-	-	-	-	-	-
INC: Replace hangers, brackets, or clamps as nec.													
LABEL, EMISSIONS, REPLACE	c3485	-	-	0.3	-	0.3	-	-	-	-	-	-	-
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	c3486	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
Common Rail Feed Pipe													
Right side	C3487	-	-	-	-	4.5	-	-	-	-	-	-	-
Left side	C3488	-	-	-	-	1	-	-	-	-	-	-	-
Fuel Common Rail													
right side	c3489	-	-	-	-	3.4	-	-	-	-	-	-	-
left side	c3490	-	-	-	-	1.4	-	-	-	-	-	-	-

HUMMER H1							ENGINE						
OPERATION DESCRIPTION	OPERATION NUMBER	ENGINE					MODEL						
		X	Y	Z/F	D/L	P	82	83 and 56	84 and 57	85	89 and 55	90 and 58	91 and 59
SOME LABOR OPERATIONS IN THIS SECTION HAVE AN ADD CONDITION "TO CLEAN PARTS ON VEHICLES OVER 30,000 MILES IF NEC." WHEN CLAIMING THIS "ADD," THE PARTICULAR LABOR OPERATION INVOLVED MUST BE CITED AS Y-TIME (ADD TIME).													
COOLING SYSTEM LEAK-ANALYZE	D4000	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
INC: Pressure test or add dye and inspect for leaks with black light. Tightening and fastening of clamps and fixtures.													
RADIATOR ASSEMBLY-REPLACE OR R&R	D4005	4	4	4	4	4.3	-	-	-	-	-	-	-
INC: Drain and Refill.													
INC: R&I Trans. Oil cooler power stg. cooler, and radiator supports.													
ADD:													
A - With A/C		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
SHROUD, RADIATOR FAN-REPLACE	D4010	3.6	3.6	3.6	3.6	3.6	-	-	-	-	-	-	-
ADD:													
A - With A/C		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
SHIELD, AIR LIFT TO SHROUD-REPLACE	D4015	3.6	3.6	3.6	3.6	-	-	-	-	-	-	-	-
ADD:													
A - With A/C		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
SUPPORT, RADIATOR-REPLACE													
left	D4016	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
right	D4017	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
CAP, SURGE TANK-REPLACE	D4020	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
INC: Diagnosis to pressure test cap.													
TANK, SURGE-REPLACE	D4025	0.4	0.4	0.4	0.4	1	-	-	-	-	-	-	-
RESERVOIR, RADIATOR COOLANT-REPLACE	D4030	-	-	-	0.4	-	-	-	-	-	-	-	-
TUBE, OVERFLOW-REPLACE	D4035	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
CLAMP, RADIATOR HOSE-REPLACE	D4040	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
HOSE, ENGINE COOLANT-REPLACE													
upper	D4045	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
lower	D4050	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
HOSE, SURGE TANK TO RADIATOR VENT-REPLACE	D4055	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
HOSE, VENT, SURGE TANK TO WATER	D4060	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
CROSSOVER-REPLACE													
HOSE, INLET, WATER PUMP-REPLACE	D4065	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-	-
TUBE ASSEMBLY, RADIATOR, LOWER-REPLACE	D4068	0.8	0.8	0.8	0.8	3	-	-	-	-	-	-	-
COCK OR PLUG, RADIATOR DRAIN-REPLACE	D4070	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-

[illegible]

INC: Cooler line flush and diagnosis time for SRTA replacement.														
INC: R&R exhaust converter, support exhaust pipe, mount trans in fixture and make nec adjustments. Align exhaust system as nec.														
ADD:														
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
B - To Replace Flywheel		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
C - 2004 Model Year		-	-	1.5	-	-	-	-	-	-	-	-	-	-
MOUNT, TRANSMISSION-REPLACE	E5070	0.3	0.3	0.3	0.3	0.7	-	-	-	-	-	-	-	-
PIPE, TRANSMISSION OIL COOLER-REPAIR OR REPLACE	E5075	1.8	1.8	1.8	1.8	1.8	-	-	-	-	-	-	-	-
PIPE, TRANSFER CASE COOLING-REPLACE	E5077	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
HOSE AND/OR CLAMPS (SUPPLY AND RETURN)-REPLACE	E5080	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
INC: Adjust														
VALVE, TRANSMISSION COOLER BYPASS-REPLACE	E5085	-	0.5	0.5	0.5	1	-	-	-	-	-	-	-	-
DIPSTICK, TRANSMISSION OIL LEVEL-REPLACE	E5090	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
TUBE AND/OR SEAL, TRANSMISSION FILLER-REPLACE	E5095	1	1	2.5	1	0.8	-	-	-	-	-	-	-	-
ADD:														
A - 2004 Model Year		-	-	1.5	-	-	-	-	-	-	-	-	-	-
LEVER, SHIFT CONTROL (AT TRANSMISSION)-REPLACE	E5100	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
INC: Adjust														
SWITCH, KICKDOWN-ADJUST	E5105	0.3	-	-	-	-	-	-	-	-	-	-	-	-
ADD:														
A - Replace		0.1	-	-	-	-	-	-	-	-	-	-	-	-
SENSOR, THROTTLE POSITION-ADJUST	E5106	-	0.4	-	-	-	-	-	-	-	-	-	-	-
ADD:														
A - Replace		-	0.3	-	-	-	-	-	-	-	-	-	-	-
BOLTS, CONVERTER TO FLYWHEEL-REPLACE	E5110	1.5	1.5	1.5	1.5	1.8	-	-	-	-	-	-	-	-
ADD:														
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
CONVERTER ASSEMBLY, TRANSMISSION-REPLACE	E5115	4.2	4.2	4.2	4.2	6.5	-	-	-	-	-	-	-	-
INC: Cooler line flush.														
INC: R&R exhaust converter, support exhaust pipe, R&R trans, check pressure and end play of converter. Align exhaust system as nec.														
NOTE: See B2170 for Cover, Torque Converter-Replace.														
ADD:														
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
B - To Replace Flywheel		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
C - 2004 Model Year		-	-	1.5	-	-	-	-	-	-	-	-	-	-
PAN AND/OR GASKET, TRANSMISSION OIL-REPLACE	E5120	0.7	1.5	1.5	1.5	0.8	-	-	-	-	-	-	-	-
INC: Clean oil pan and service screen.														
ADD:														
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
FILTER, EXTERNAL, TRANSMISSION- REPLACE	E5121	-	-	-	-	0.2	-	-	-	-	-	-	-	-
SENSOR ASSEMBLY, SPEED INPUT-REPLACE	E5125	-	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
SENSOR ASSEMBLY, SPEED OUPUT-REPLACE	E5130	-	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-

[illegible]

A - W/Skid Plate		0.1	0.1	0.1	0.1	-	-	-	-	-	-	-	-
TRANSFER CASE ASSEMBLY-REPLACE	E5215	3.5	3.5	3.5	3.5	3	-	-	-	-	-	-	-
POLICY: A													
ADD:													
A - W/Skid Plate		0.1	0.1	0.1	0.1	-	-	-	-	-	-	-	-
TRANSFER CASE ASSEMBLY-RECONDITION	E5220	6.2	6.2	6.2	6.2	5.8	-	-	-	-	-	-	-
POLICY: A													
ADD:													
A - W/Skid Plate		0.1	0.1	0.1	0.1	-	-	-	-	-	-	-	-
cooler, transfer case-replace	E5223	3	3	3	3	3.1	-	-	-	-	-	-	-
ADD:													
A - W/Skid Plate		0.1	0.1	0.1	0.1	-	-	-	-	-	-	-	-
SENSOR, TRANSFER CASE SPEED-REPLACE	E5225	-	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
PLUG, DUST, TRANSFER CASE-REPLACE	E5226	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
SEAL, TRANSFER CASE OUTPUT OIL-REPLACE													
front	E5230	1	1	1	1	1	-	-	-	-	-	-	-
rear	E5235	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
GASKET OR SEALER, TRANSFER CASE REAR OUTPUT SHAFT HOUSING-REPLACE	E5240	1	1	1	1	1	-	-	-	-	-	-	-
HOUSING, REAR OUTPUT SHAFT-REPLACE	E5245	1	1	1	1	1	-	-	-	-	-	-	-
CABLE, TRANSFER CASE GUIDE	E5250	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	E5255	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
SWITCH, NEUTRAL START BACK-UP -REPLACE	E5256	-	-	-	-	0.6	-	-	-	-	-	-	-

HUMMER H1							Wheels, Tires & CTIS						
OPERATION DESCRIPTION	OPERATION NUMBER	ENGINE					MODEL						
		X	Y	Z/F	D/L	P	82	83 and 56	84 and 57	85	89 and 55	90 and 58	91 and 59
SOME LABOR OPERATIONS IN THIS SECTION HAVE AN ADD CONDITION "TO CLEAN PARTS ON VEHICLES OVER 30,000 MILES IF NEC." WHEN CLAIMING THIS "ADD," THE PARTICULAR LABOR OPERATION INVOLVED MUST BE CITED AS Y-TIME (ADD TIME).													
WHEEL-BALANCE													
INC: R&R wheel and tire.													
one	F6000	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
two	F6001	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
four	F6002	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
ADD:													
A - W/CTIS (Each)		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
B - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
C - 2006 Model Year (Each)		-	-	-	-	0.2	-	-	-	-	-	-	-
WHEEL, aluminum, one-piece-replace													
one	F6008	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
ADD:													
A - To Replace Each Additional		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
B - W/CTIS (Each)		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
WHEEL, STEEL, ONE-PIECE-REPLACE													
INC: Replacement of valve stem if nec and balance of assy.													
one	F6005	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-	-
ADD:													
A - To Replace Each Additional		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
B - To Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
C - W/CTIS (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
WHEEL-R&R OR REPLACE													
INC: Balance													
two piece STEEL wheel	F6007	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-	-
ADD:													
A - To Replace Each Additional		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
B - W/CTIS (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
C - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
two piece ALUMINUM wheel	F6011	-	-	1.1	-	1.1	-	-	-	-	-	-	-
ADD:													
A - To Replace Each Additional		-	-	0.7	-	0.7	-	-	-	-	-	-	-
B - W/CTIS (Each)		-	-	0.2	-	0.2	-	-	-	-	-	-	-

WHEEL, CENTERING WASHER (PER WHEEL)-REPLACE	F6010	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
A - W/CTIS (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
B - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
TIRE-REPLACE													
POLICY: a													
INC: Balance													
one	F6019	1.1	1.1	1.1	1.1	1.1	-	-	-	-	-	-	-
ADD:													
A - To Replace Each Additional		0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
B - W/CTIS (Each)		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
C - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
STUD, INNER RIM-REPLACE (minimum 3 studs)	F6024	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
INC: R&R wheel and tire assy.													
ADD:													
A - W/CTIS (Each)		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
B - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
C - Each Additional Stud		0.1	0.1	0.1	0.1	0.1	-	-	-	-	-	-	-
RUNFLAT ASSEMBLY (ONE PIECE OR TWO PIECE)-REPLACE	F6029	1.1	1.1	1.1	1.1	1.1	-	-	-	-	-	-	-
ADD:													
A - W/CTIS (Each)		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
B - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
BEADLOCK ASSEMBLY (ONE PIECE OR TWO PIECE)-REPLACE	F6034	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
ADD:													
A - W/CTIS (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
B - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
STUD, WHEEL MOUNTING-REPLACE	F6039	0.4	0.4	0.4	0.4	0.6	-	-	-	-	-	-	-
INC: R&R wheel													
ADD:													
A - W/CTIS (Each)		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
B - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
WHEEL, PACKING (O-RING) (TWO PIECE WHEEL ONLY)-REPLACE	F6044	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
INC: Balance													
ADD:													
A - W/CTIS (Each)		0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
B - Paint Wheel (Each)		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
FRONT AXLE DIFFERENTIAL AND GEARED HUB VENT LINES-REPLACE													
geared hub vent line													
left hand	F6049	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
right hand	F6050	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
union to tee													
left hand	F6051	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
tee to tee	F6052	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
differential vent line	F6053	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
tee to rail	F6054	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-

ADD:														
A - Drain, Flush and Refill (if required)		0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
REAR AXLE DIFFERENTIAL AND GEARED HUB VENT LINES-REPLACE														
geared hub vent line														
left hand	F6060	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
right hand	F6061	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
tee to tee	F6062	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
differential vent line	F6063	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
tee to elbow	F6064	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
ADD:														
A - Drain, Flush and Refill (if required)		0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
VENT LINES, TRANSMISSION-REPLACE														
tee to tee	F6070	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
tee to transmission	F6071	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
tee to t-case	F6072	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
ADD:														
A - Drain, Flush and Refill (if required)		0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
VENT LINES-CENTRAL VENTING SYSTEM-REPLACE														
filter to elbow	F6077	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
elbow to tee	F6078	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
fuel vent lines														
tee to main tank	F6080	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
tee to aux tank	F6081	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
tank to fill tube	F6082	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
rollover to fill housing	F6083	1.3	1.3	1.3	1.3	1.3	-	-	-	-	-	-	-	-
rollover to tee	F6084	1.3	1.3	1.3	1.3	1.3	-	-	-	-	-	-	-	-
canister to tee	F6085	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
ADD:														
A - Drain, Flush and Refill (if required)		0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
VENT LINE, WINCH-REPLACE														
winch to tee	F6090	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-	-
GEARED HUB, ASSEMBLY-REPLACE	F6093	1.4	1.4	1.4	1.4	1.4	-	-	-	-	-	-	-	-
POLICY: A														
COVER, SIDE, GEARED HUB-REPLACE	F6097	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
SEAL, GEARED HUB-REPLACE														
any one seal (input, output, spindle) on same hub	f6094	1.3	1.3	1.3	1.3	1.3	-	-	-	-	-	-	-	-
ADD:														
A - Each additional seal (input, output, spindle) on same hub		0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
STEERING ARM COVER-REPLACE	F6100	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
STEERING ARM COVER-RESEAL	F6101	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
GEARED HUB, ASSEMBLY-R&R	F6103	1.4	1.4	1.4	1.4	1.4	-	-	-	-	-	-	-	-
POLICY: A														
ADD:														
A - Outer Bearing		0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-	-

B - Inner Bearing		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
C - Clamp Nut		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
D - Recondition		2.2	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-
CARRIER COMPONENTS, SWING AWAY SPARE TIRE-REPLACE													
frame assembly	F6107	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
bracket and/or reinforcement	F6108	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
lock pin and/or cable	F6109	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
bracket striker	F6110	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
plug or cap	F6111	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
spindle-REPLACE	F6112	1.4	1.4	1.4	1.4	1.4	-	-	-	-	-	-	-
policy: a													
CARRIER, COMPONENTS, BED MOUNT SPARE TIRE-REPLACE													
frame	F6116	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
bracket	F6117	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
HOLD DOWN, JACK AND/OR TRIANGLE KIT- R&R OR REPLACE	F6122	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
JACK AND/OR HANDLE-REPLACE	F6127	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
VALVE, SCHRADER-REPLACE													
one wheel	F6132	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
CTIS (AIR LEAK) TEST	F6134	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
MANIFOLD ASSEMBLY, CTIS-REPLACE	F6137	-	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
VALVE INFLATE, CTIS-REPLACE													
one	F6142	0.6	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
both	F6148	-	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
VALVE, DEFLATE, CTIS-REPLACE													
one	F6147	0.3	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
VALVE, SAFETY, CTIS-REPLACE	F6153	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
SWITCH, PRESSURE, CTIS-REPLACE													
one	F6158	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
both	F6159	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
COIL assembly, inflate, ctis-replace													
front	F6164	-	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
rear	F6165	-	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
COIL ASSEMBLY, DEFLATE, CTIS-REPLACE	F6170	-	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
DUST EXCLUDER, CTIS-REPLACE	F6175	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
MANIFOLD, CTIS-REPLACE	F6180	-	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
BRACKET ASSEMBLY, VALVE MOUNTING, CTIS-REPLACE	F6185	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
VALVE ASSEMBLY, TANK, CTIS-REPLACE	F6190	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
HOSE ASSEMBLY, AUXILIARY AIR, CTIS-REPLACE	F6195	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
COMPRESSOR, CTIS-REPLACE	F6200	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
BRACKET ASSEMBLY, LOWER, CTIS-REPLACE	F6205	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
BRACKET ASSEMBLY, ISOLATOR, CTIS-REPLACE													
one	F6208	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-

	two	F6209	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	all	F6210	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
BRACKET ASSEMBLY, UPPER, CTIS-REPLACE		F6215	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
FUSE HOLDER, CTIS-REPLACE		F6220	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
FUSE, CTIS-REPLACE		F6225	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
FUSE COVER, CTIS-REPLACE		F6230	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
CLAMP, COMPRESSOR MOUNTING CTIS-REPLACE														
	one	F6235	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
	both	F6236	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
HOSE, AIR HORN TO COMPRESSOR, CTIS-REPLACE		F6241	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
TUBING, MANIFOLD TO COMPRESSOR, CTIS-REPLACE		F6246	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
TUBING, MANIFOLD TO GAUGE, CTIS-REPLACE														
	one	F6251	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
	both	F6252	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
HOSE ASSEMBLY, TEE TO R.H. SIDE, REAR, CTIS-REPLACE		F6257	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
HOSE ASSEMBLY, TEE TO L.H. SIDE, FRONT AND REAR, CTIS-REPLACE		F6262	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
HOSE ASSEMBLY, VALVE TO REAR TEE, CTIS-REPLACE		F6267	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
HOSE ASSEMBLY, VALVE TO FRONT TEE, CTIS-REPLACE		F6272	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
HOSE ASSEMBLY, FRONT TEE TO RIGHT SIDE, CTIS-REPLACE		F6274	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
HOSE, QUICK DISCONNECT TO TIRE VALVE, CTIS-REPLACE		F6277	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
SHIELD, VALVE ASSEMBLY, CTIS-REPLACE		F6282	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
DECAL, LOGO, CTIS-REPLACE		F6287	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
VALVE ASSEMBLY, QUICK DISCONNECT, CTIS-REPLACE		F6292	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
BRACKET, WHEEL TUBE SHIELD SUPPORT, CTIS-REPLACE		F6297	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
SEAL, AIR INTAKE HOSE, CTIS-REPLACE		F6302	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
VALVE, CHECK, CTIS-REPLACE		F6307	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
VALVE TUBE, DEFLATE VALVE TO SELECTOR, CTIS-REPLACE		F6312	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
SHIELD, REAR TUBE CONNECTION, CTIS-REPLACE		F6317	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
TUBE, SELECTOR TO UNION, CTIS-REPLACE		F6322	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
TUBE, SELECTOR TO FRONT TEE, CTIS-REPLACE		F6327	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
VALVE, TIRE SELECT, CTIS-REPLACE		F6332	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
ADD:														
A - 1995 Below			1	1	-	1	-	-	-	-	-	-	-	-
HANDLE, VALVE, TIRE SELECT, CTIS-REPLACE		F6337	0.2	0.2	-	0.2	-	-	-	-	-	-	-	-
TUBE, TEE TO SELECTOR, CTIS, -REPLACE		F6342	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
TUBE, TEE TO UNION, CTIS-REPLACE		F6347	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
BOLTS, FASTENERS, FITTINGS (TIGHTEN)		F6352	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-

[illegible]

A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
RESERVOIR, COVER MASTER CYLINDER-REPLACE	H7056	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
CYLINDER, BRAKE MASTER-REPLACE	H7061	1.3	1.3	1.3	1.3	1.3	-	-	-	-	-	-	-
INC: Bleed brake system.													
BRAKE SYSTEM-BLEED	H7066	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
INC: D&C pressure bleeder, bleed master cyl as nec.													
VALVE, PORPORTIONING-REPLACE	H7071	1	1	1	1	-	-	-	-	-	-	-	-
PIPE, BRAKE-REPLACE													
MASTER CYL TO PORPORTIONING VALVE													
FRONT	H7076	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
REAR	H7077	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
PORPORTIONING VALVE TO FRONT TEE	H7078	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
TEE TO FRONT CALIPER													
LEFT	H7080	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
RIGHT	H7081	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
PORPORTIONING VALVE TO REAR TEE													
FRONT	H7082	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
REAR	H7083	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
REAR TEE TO CALIPER													
LEFT	H7084	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
RIGHT	H7085	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
master cylinder to abs modulator													
front	H7072	-	-	0.3	-	0.3	-	-	-	-	-	-	-
rear	H7073	-	-	0.3	-	0.3	-	-	-	-	-	-	-
abs modulator to front caliper													
left	H7074	-	-	0.6	-	0.9	-	-	-	-	-	-	-
right	H7075	-	-	0.6	-	0.9	-	-	-	-	-	-	-
abs modulator to rear union													
left	H7079	-	-	0.6	-	0.9	-	-	-	-	-	-	-
right	H7089	-	-	0.6	-	0.9	-	-	-	-	-	-	-
rear union to rear caliper													
left	H7087	-	-	0.5	-	0.8	-	-	-	-	-	-	-
right	H7088	-	-	0.5	-	0.8	-	-	-	-	-	-	-
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
INC: D&C pressure bleeder, bleed master cyl as nec.													
ADAPTER, BRAKE PIPE TO MODULATOR-REPLACE													
one	H7086	-	-	0.6	-	0.6	-	-	-	-	-	-	-
ADD: Each Additional		-	-	0.1	-	0.1	-	-	-	-	-	-	-
INC: D&C pressure bleeder, bleed master cyl as nec.													
BOOSTER ASSEMBLY, HYDRAULIC POWER BRAKE-REPLACE	H7092	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
INC: Bleed power steering system.													
PEDAL AND/OR BUSHING, BRAKE-R&R OR REPLACE	H7097	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
SPRING, BRAKE PEDAL RETURN-REPLACE	H7102	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
BRAKE, PARKING-ADJUST	H7107	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-

LEVER, PARKING BRAKE-REPLACE	H7112	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
CABLE, AND/OR ROD PARKING BRAKE-REPLACE													
rod	H7117	0.6	0.6	0.6	0.6	0.9	-	-	-	-	-	-	-
cable													
left	H7118	0.8	0.8	0.8	0.8	1.1	-	-	-	-	-	-	-
right	H7119	0.8	0.8	0.8	0.8	1.1	-	-	-	-	-	-	-
both	H7120	1.4	1.4	1.4	1.4	1.7	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
EQUALIZER BAR, PARKING BRAKE-REPLACE	H7125	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
BRACKET, PARKING BRAKE CABLE MOUNTING-REPLACE													
left	H7130	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
right	H7131	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
SPRING, BRAKE ROD, ANTI-RATTLE-REPLACE	H7136	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
BOOT, DUST AND MOISTURE BARRIER, PARK BRAKE-REPLACE	H7141	1	1	1	1	1	-	-	-	-	-	-	-
STRIKER, BRAKE LIGHT SWITCH-REPLACE	H7146	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
MODULATOR, ABS-REPLACE	H7147	-	-	1.7	-	1.7	-	-	-	-	-	-	-
POLICY: A													
INC: D&C Pressure Bleeder, Bleed Master Cylinder as nec.													
ECU, ABS-REPLACE	H7148	-	-	0.5	-	0.5	-	-	-	-	-	-	-
POLICY: A													
SENSOR AND SLEEVE, ABS WHEEL SPEED	H7149	-	-	0.5	-	0.5	-	-	-	-	-	-	-
SLEEVE, SENSOR, ABS WHEEL SPEED	H7150	-	-	0.2	-	0.2	-	-	-	-	-	-	-
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	H7151	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
BRACKET, SENSOR, WHEEL SPEED	H7152	-	-	0.5	-	0.5	-	-	-	-	-	-	-

A - To Adjust Toe-In		0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
STEERING, STOPS-REPLACE	J8075	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
adjust	J8076	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
POWER STEERING SYSTEM, PRESSURE/FLOW-TEST	J8080	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
POWER STEERING SYSTEM, LEAK-TEST	J8085	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
INC: Add dye, run engine, inspect for leaks with blacklight.													
PULLEY, POWER STEERING PUMP-REPLACE	J8090	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
BRACKET, POWER STEERING PUMP ASSEMBLY-REPLACE	J8100	1.5	1	1	1	1	-	-	-	-	-	-	-
PUMP ASSEMBLY, POWER STEERING-REPLACE	J8105	1.2	1.2	1.2	1.2	1.3	-	-	-	-	-	-	-
PUMP ASSEMBLY, POWER STEERING-R&R	J8110	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
ADD:													
A - To Recondition Pump		0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
VALVE, POWER STEERING PUMP FLOW	J8120	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
CONTROL-REPLACE													
CAP, POWER STEERING PUMP RESERVOIR-REPLACE	J8125	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
SEAL, POWER STEERING PUMP SHAFT, OIL-REPLACE	J8130	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
RESERVOIR ASSEMBLY, POWER STEERING FLUID (REMOTE)-REPLACE	J8135	-	0.6	-	0.6	-	-	-	-	-	-	-	-
1999 Model year and above	J8134	-	-	0.6	-	0.6	-	-	-	-	-	-	-
HOSES, POWER STEERING HYDRAULIC-REPLACE													
reservoir to pump	J8136	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
return, gear to cooling pipe	J8137	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
return, cooling pipe to reservoir	J8138	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
LINE, PRESSURE BOOSTER TO PUMP	J8140	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
HYDRAULIC-REPLACE													
LINE, PRESSURE BOOSTER TO STEERING GEAR	J8145	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
HYDRAULIC-REPLACE													
HOSE, RETURN BOOSTER TO PUMP HYDRAULIC-REPLACE	J8150	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
INC: Bleed system.													
COOLER, POWER STEERING OIL	J8155	1	1	1	1	0.7	-	-	-	-	-	-	-
HYDRAULIC-REPLACE													
INC: Check oil level, fill and bleed system as required.													
GEAR ASSEMBLY, POWER STEERING-REPLACE	J8160	0.8	0.8	0.8	0.8	2.5	-	-	-	-	-	-	-
POLICY: A													
GEAR ASSEMBLY, POWER STEERING-R&R	J8165	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-	-
INC: Adjust gear.													
ADD:													
A - To Replace Side Cover and/or "O" Ring Seal		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
B - To Replace End Cover and/or "O" Ring Seal		0.1	0.1	0.1	0.1	-	-	-	-	-	-	-	-
C - To R&R Pitman Shaft or Bearing		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
D - To Recondition Adjuster Plug Assembly		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
E - To Recondition Valve Body Assembly		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
F - To Recondition Rack Piston Assembly		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
G - To Replace Housing		0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-

H - To Recondition P/S Gear (Complete)		1	1	1	1	-	-	-	-	-	-	-	-
INC: All ADD Conditions.													
SEAL, PITMAN SHAFT-REPLACE	J8170	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-	-
GEAR ASSEMBLY, POWER STEERING-ADJUST	J8175	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	J8180	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-

HUMMER H1							Axles, Suspension & Frame						
OPERATION DESCRIPTION	OPERATION NUMBER	ENGINE					MODEL						
		X	Y	Z/F	D/L	P	82	83 and 56	84 and 57	85	89 and 55	90 and 58	91 and 59
SOME LABOR OPERATIONS IN THIS SECTION HAVE AN ADD CONDITION "TO CLEAN PARTS ON VEHICLES OVER 30,000 MILES IF NEC." WHEN CLAIMING THIS "ADD," THE PARTICULAR LABOR OPERATION INVOLVED MUST BE CITED AS Y-TIME (ADD TIME).													
RAILS, FRAME-REPLACE													
POLICY: A													
left	K9000	14	14	14	14	14	-	-	-	-	-	-	-
right	K9001	13	13	13	13	13	-	-	-	-	-	-	-
both	K9002	24	24	24	24	24	-	-	-	-	-	-	-
FRAME, EXTENSIONS-REPLACE													
INC: Brace Assy. (with winch only)													
left	K9005	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
right	K9006	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
both	K9007	2.4	2.4	2.4	2.4	2.4	-	-	-	-	-	-	-
BRACE, FRONT SUSPENSION-REPLACE													
left	K9010	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
right	K9011	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
both	K9012	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
BRACKET, SPLASH SHIELD-REPLACE													
left	K9015	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
right	K9016	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
both	K9017	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
BRACKET, FRONT SUSPENSION, CROSSMEMBER-REPLACE													
front, front													
left	K9020	3.2	3.2	3.2	3.2	3.2	-	-	-	-	-	-	-
right	K9021	3.2	3.2	3.2	3.2	3.2	-	-	-	-	-	-	-
both	K9022	4.5	4.5	4.5	4.5	4.5	-	-	-	-	-	-	-
front, rear													
left	K9023	3.2	3.2	3.2	3.2	3.2	-	-	-	-	-	-	-
right	K9024	3.2	3.2	3.2	3.2	3.2	-	-	-	-	-	-	-
both	K9025	4.5	4.5	4.5	4.5	4.5	-	-	-	-	-	-	-
BRACKET, LOWER RADIATOR MOUNT-REPLACE	K9030	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
CROSSMEMBER-REPLACE													
POLICY: A													
front													
forward	K9035	8	8	8	8	8	-	-	-	-	-	-	-

	rear	K9040	14.4	14.4	14.4	14.4	14.4	-	-	-	-	-	-	-
	both	K9041	15.4	15.4	15.4	15.4	15.4	-	-	-	-	-	-	-
BRACKET, AXLE SUPPORT, FRONT-REPLACE														
	left	K9045	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
	right	K9046	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
	both	K9047	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
BUMPER, FRONT-REPLACE														
POLICY: A														
BRACKET, FRONT BUMPER-REPLACE														
	left	K9055	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
	right	K9056	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
	both	K9057	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
SHACKLE, LIFTING, BRACKET (FRONT OR REAR)-REPLACE														
	left	K9060	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
	right	K9061	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
	both	K9062	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
SHACKLE, LIFTING (FRONT OR REAR)-REPLACE														
	one	K9065	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
	both	K9066	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
BRACKET, ENGINE MOUNT-REPLACE														
	left	K9070	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
	right	K9071	2.4	2.4	2.4	2.4	2.4	-	-	-	-	-	-	-
BRACKET, FRONT LICENSE PLATE-REPLACE														
BRACKET, REAR LICENSE PLATE-REPLACE														
	with guard	K9077	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
BRACKET, AIRLIFT-REPLACE														
	left	K9080	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
	right	K9081	1.2	1.5	1.5	1.5	1.5	-	-	-	-	-	-	-
SEAL, AIRLIFT BRACKET-REPLACE														
INC: Closeout														
	left	K9085	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
	right	K9086	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
BRACKET, COOLING LINE SUPPORT-REPLACE														
BRACKET, UPPER CONTROL ARM, FRONT-REPLACE														
	left													
	front	K9093	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
	rear	K9094	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
	both	K9095	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
	right													
	front	K9096	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
	rear	K9097	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
	both	K9098	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
BRACKET, VENT TUBE-REPLACE														
Alignment Cam Washer/bolt, Front-replace														
		K9100	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
		K9099	-	0.5	0.5	-	0.5	-	-	-	-	-	-	-

(VIN 179093 and above)														
BRACKET, BODY MOUNT, FRONT-REPLACE														
	left	K9105	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
	right	K9106	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
	both	K9107	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
BRACKET, BODY MOUNT, REAR-REPLACE														
	left	K9110	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	right	K9111	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	both	K9112	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
BRACKET, TRANSMISSION SUPPORT-REPLACE														
	left	K9115	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	right	K9116	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
	both	K9117	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
BRACKET, CATALYTIC CONVERTER MOUNTING-REPLACE		K9120	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
BRACKET, TIE DOWN, FRAME ASSEMBLY (FRONT OR REAR)-REPLACE														
	left	K9125	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	right	K9126	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	both	K9127	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
CROSSMEMBER, REAR SUSPENSION-REPLACE														
POLICY: A														
	front	K9130	12	12	12	12	12	-	-	-	-	-	-	-
	rear	K9131	7.2	7.2	7.2	7.2	7.2	-	-	-	-	-	-	-
	both	K9132	13	13	13	13	13	-	-	-	-	-	-	-
PLATE, VENT LINES, TUBE MOUNTING-REPLACE		K9135	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
BRACKET, REAR SUSPENSION-REPLACE														
	front													
	left	K9140	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	right	K9141	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	both	K9142	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
	rear													
	left	K9143	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	right	K9144	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	both	K9145	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
BRACKET, REAR AXLE SUPPORT-REPLACE														
	left	K9150	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
	right	K9151	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
	both	K9152	1.7	1.7	1.7	1.7	-	-	-	-	-	-	-	-
BRACKET, REAR AXLE SUPPORT, INPUT-REPLACE		K9155	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
SUPPORT, REAR BUMPER-REPLACE														
INC: Spacer														
	left	K9159	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
	right	K9160	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-

	both	K9161	1	1	1	1	1	-	-	-	-	-	-	-
BRACKET, REAR BUMPER MOUNTING ASSEMBLY-REPLACE														
	left	K9165	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	right	K9166	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	both	K9167	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
rear BUMPER closeout-REPLACE		K9168	-	-	-	-	0.5	-	-	-	-	-	-	-
BUMPER, REAR-REPLACE		K9170	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
POLICY: A														
ADD:														
A - Trailer hitch			0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
BRACKET, SKID PLATE MOUNTING-REPLACE														
	left	K9175	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
	right	K9176	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
	both	K9177	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
SKID PLATE, AUXILIARY FUEL TANK-REPLACE		K9180	-	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
FRAME, REINFORCEMENT-REPLACE														
INC: Plates														
	left	K9185	2	2	2	2	2	-	-	-	-	-	-	-
	right	K9186	2	2	2	2	2	-	-	-	-	-	-	-
	both	K9187	3.7	3.7	3.7	3.7	3.7	-	-	-	-	-	-	-
BRACKET, UPPER CONTROL ARM, REAR-REPLACE														
	front													
	left	K9190	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
	right	K9191	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
	both	K9192	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
	rear													
	left	K9195	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
	right	K9196	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
	both	K9197	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
Alignment Cam Washer/bolt, Rear-replace		k9198	-	0.5	0.5	-	-	-	-	-	-	-	-	-
VIN 179093 AND ABOVE														
for those operations in this section which require a wheel alignment, the times from k9245 can be claimed only once per repair order.														
BRACE, BUMPER, REAR-REPLACE		K9200	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
LINK, FRONT STABILIZER SHAFT AT CONTROL ARM-REPLACE														
	left	K9205	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	right	K9206	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
	both	K9207	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
shaft, front stabilizer-replace		K9210	0.7	0.7	0.7	0.7	1	-	-	-	-	-	-	-
INC: R&R links and bushings.														
ADD:														
A - W/Driveline Protection			0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-

INSULATOR AND/OR BRACKET, FRONT		K9215	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
STABILIZER SHAFT AT FRAME-REPLACE														
INC: One or both sides.														
BRUSHGUARD-REPLACE		K9230	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
BRACKET, BRUSHGUARD SUPPORT-REPLACE		K9235	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
PIN ASSEMBLY, BRUSHGUARD-REPLACE		K9237	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
toe-adjust														
front		K9240	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
rear		K9241	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
WHEEL ALIGNMENT-CHECK AND/OR ADJUST		K9245	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
POLICY: A														
INC: Adjust tire pressure as required. Check caster, camber, toe and ride height.														
ADD:														
A - Adjust Front			2	2	2	2	2	-	-	-	-	-	-	-
B - Adjust Rear			2	2	2	2	2	-	-	-	-	-	-	-
SPRINGS, COIL-REPLACE														
POLICY: A														
front														
left		K9250	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
right		K9251	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
both		K9252	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
rear														
left		K9253	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
right		K9254	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
both		K9255	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
SHOCK ABSORBER-REPLACE														
POLICY: A														
front														
left		K9260	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
right		K9261	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
both		K9262	1	1	1	1	1	-	-	-	-	-	-	-
rear														
left		K9263	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
right		K9264	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
both		K9265	1	1	1	1	1	-	-	-	-	-	-	-
SEAT, UPPER SPRING-REPLACE														
front														
left		K9270	1.1	1.1	1.1	1.1	1.1	-	-	-	-	-	-	-
right		K9271	1.1	1.1	1.1	1.1	1.1	-	-	-	-	-	-	-
both		K9272	2	2	2	2	2	-	-	-	-	-	-	-
rear														
left		K9273	1.1	1.1	1.1	1.1	1.1	-	-	-	-	-	-	-
right		K9274	1.1	1.1	1.1	1.1	1.1	-	-	-	-	-	-	-

both	K9275	2	2	2	2	2	-	-	-	-	-	-	-
ARM ASSEMBLY, CONTROL-REPLACE													
POLICY: A													
front upper													
left	K9280	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
right	K9281	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
both	K9282	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
rear upper													
left	K9283	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
right	K9284	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
both	K9285	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
front lower													
left	K9286	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
right	K9287	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
both	K9288	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
rear lower													
left	K9289	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
right	K9290	0.9	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-
both	K9291	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
BUSHINGS, CONTROL ARM-REPLACE													
front upper													
left	K9295	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
right	K9296	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
both	K9297	2.2	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-
rear upper													
left	K9298	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
right	K9299	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
both	K9300	2.2	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-
front lower													
left	K9301	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
right	K9302	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
both	K9303	2.2	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-
rear lower													
left	K9304	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
right	K9305	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
both	K9306	2.2	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-
BALL JOINT-REPLACE													
POLICY: A													
front upper													
left	K9310	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
right	K9307	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
both	K9315	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
rear upper													
left	K9311	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-

right	K9308	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
both	K9316	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
front lower													
left	K9313	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
right	K9309	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
both	K9317	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
rear lower													
left	K9314	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
right	K9312	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
both	K9318	1.6	1.6	1.6	1.6	1.6	-	-	-	-	-	-	-
RODS, REAR RADIUS (ASSEMBLY)-REPLACE													
left	K9320	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
right	K9321	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
both	K9322	1	1	1	1	1	-	-	-	-	-	-	-
RODS, REAR RADIUS-REPLACE													
bushing, tie rod													
left	K9325	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
right	K9326	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
both	K9327	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
tie rod end													
left	K9328	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
right	K9329	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
both	K9330	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
radius rod													
left	K9331	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
right	K9332	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
both	K9333	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
clamps (each)	K9334	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
BEARING, CENTER SUPPORT-REPLACE		K9340	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection			0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
SLIP JOINT, PROPELLER SHAFT-REPLACE		K9345	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
NOTE: Slip yoke/slip joint.													
ADD:													
A - W/Driveline Protection			0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
UNIVERSAL JOINT, PROPELLER SHAFT-REPLACE													
rear propeller shaft													
one	K9350	1	1	1	1	1	-	-	-	-	-	-	-
both	K9351	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-
ADD:													
A - To Replace Slip Joint (Yoke)			0.1	0.1	0.1	0.1	-	-	-	-	-	-	-
front propeller shaft													
one	K9354	1	1	1	1	1	-	-	-	-	-	-	-
two	K9355	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-

	LEFT	K9403	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
	RIGHT	K9404	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
	BOTH	K9405	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
AXLE (FRONT OR REAR)-FLUSH		K9410	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
INC: Drain, flush and refill														
SIDE BRACKETS, AXLE MOUNTING-REPLACE														
	FRONT													
	LEFT	K9415	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
	RIGHT	K9416	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
	BOTH	K9417	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-	-
	REAR													
	LEFT	K9418	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
	RIGHT	K9419	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
	BOTH	K9420	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-	-
ADD:														
A - W/Driveline Protection			0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
BRACKET, AXLE PINION MOUNT-REPLACE														
	front	K9425	0.5	0.5	0.5	0.5	0.8	-	-	-	-	-	-	-
	rear	K9426	0.4	0.4	0.4	0.4	0.7	-	-	-	-	-	-	-
ADD:														
A - W/Driveline Protection			0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
AXLE ASSEMBLY (COMPLETE)-REPLACE														
POLICY: A														
	front differential	K9435	2.3	2.3	2.3	2.3	2.6	-	-	-	-	-	-	-
	rear differential	K9436	3	3	3	3	3.3	-	-	-	-	-	-	-
ADD:														
A - W/Driveline Protection			0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
AXLE ASSEMBLY-R&R														
POLICY: A														
	front differential	K9440	2.3	2.3	2.3	2.3	2.3	-	-	-	-	-	-	-
	rear differential	K9441	3	3	3	3	3	-	-	-	-	-	-	-
ADD:														
A - W/Driveline Protection			0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
B - To Replace Side Bearings			1.8	1.8	1.8	1.8	1.8	-	-	-	-	-	-	-
C - To Replace Pinion Bearings			2.2	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-
D - To Replace Ring Gear and Pinion			2.4	2.4	2.4	2.4	2.4	-	-	-	-	-	-	-
E - To Replace Case			2.2	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-
F - To Replace Carrier			2.2	2.2	2.2	2.2	2.2	-	-	-	-	-	-	-
INC: Transfer all parts.														
G - To Recondition Carrier Complete			2.5	2.5	2.5	2.5	2.5	-	-	-	-	-	-	-
H - W/E Locker			-	-	0.1	-	0.1	-	-	-	-	-	-	-
SEAL, AXLE OUTPUT SHAFT-REPLACE														
	front axle													
	left	K9445	0.8	0.8	0.8	0.8	1.1	-	-	-	-	-	-	-

right	K9446	0.8	0.8	0.8	0.8	1.1	-	-	-	-	-	-	-
both	K9447	1.5	1.5	1.5	1.5	1.8	-	-	-	-	-	-	-
rear axle													
left	K9448	1	1	1	1	1.3	-	-	-	-	-	-	-
right	K9449	1	1	1	1	1.3	-	-	-	-	-	-	-
both	K9450	1.7	1.7	1.7	1.7	2	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
B - 1995-Below per Seal		0.3	0.3	-	0.3	-	-	-	-	-	-	-	-
C - VIN 177948-Above per Seal		-	0.3	0.3	-	-	-	-	-	-	-	-	-
COVER AND/OR GASKET, AXLE-REPLACE													
INC: Drain and refill diff. Clean and replace gasket.													
front differential	K9455	0.6	0.6	0.6	0.6	0.9	-	-	-	-	-	-	-
rear differential	K9456	0.6	0.6	0.6	0.6	0.9	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
SEAL, PINION SHAFT OIL-REPLACE													
INC: D&C propeller shaft and replace flange if nec. Reset bearing preload. R&R pinion seal and add lubricant.													
front differential	K9460	1.2	1.2	1.2	1.2	1.5	-	-	-	-	-	-	-
rear differential	K9461	0.7	0.7	0.7	0.7	1	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
FLANGE, PINION SHAFT-REPLACE													
INC: Reset bearing preload. R&R pinion seal and add lubricant.													
front differential	K9465	1	1	1	1	1.3	-	-	-	-	-	-	-
rear differential	K9466	0.5	0.5	0.5	0.5	0.8	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
SEAL, WASHER, OUTPUT FLANGE-REPLACE													
front axle													
left	K9471	0.5	0.5	0.5	0.5	0.8	-	-	-	-	-	-	-
right	K9472	0.5	0.5	0.5	0.5	0.8	-	-	-	-	-	-	-
both	K9473	0.9	0.9	0.9	0.9	1.2	-	-	-	-	-	-	-
rear axle													
left	K9474	0.5	0.5	0.5	0.5	0.8	-	-	-	-	-	-	-
right	K9475	0.5	0.5	0.5	0.5	0.8	-	-	-	-	-	-	-
both	K9476	0.9	0.9	0.9	0.9	1.2	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
FLANGE, OUTPUT, AXLE-REPLACE													
front axle													
left	K9480	0.7	0.7	0.7	0.7	1	-	-	-	-	-	-	-
right	K9481	0.7	0.7	0.7	0.7	1	-	-	-	-	-	-	-

both	K9482	1.3	1.3	1.3	1.3	1.6	-	-	-	-	-	-	-
rear axle													
left	K9483	0.7	0.7	0.7	0.7	1	-	-	-	-	-	-	-
right	K9484	0.7	0.7	0.7	0.7	1	-	-	-	-	-	-	-
both	K9485	1.3	1.3	1.3	1.3	1.6	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
VENT HOSE AND FITTINGS, AXLE (FRONT OR REAR)-REPLACE	F6063	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
INC: Hose assy.													
ADD:													
A - Drain, Flush and Refill		0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
SKID PLATE, W OR W/O WINCH-REPLACE	M10693	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
POLICY: A													
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	K9470	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
DRIVELINE PROTECTION-REPLACE													
POLICY: A													
rear	M10777	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
front	M10778	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
middle	M10779	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
side bracket	M10780	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
aux. fuel tank	M10781	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
t-case skid plate	M10782	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1

front	M10035	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5	0.5
rear	M10036	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5	0.5
right													
front	M10037	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5	0.5
rear	M10038	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5	0.5
HANDLE, FRONT DOOR WINDOW REGULATOR-REPLACE													
left	M10040	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2	0.2
right	M10041	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2	0.2
REGULATOR, FRONT DOOR WINDOW-R&R OR REPLACE													
INC: D&C glass, prop in up position and transfer motor where nec.													
left manual	M10045	-	-	-	-	-	0.6	0.6	0.6	-	0.6	0.6	0.6
right manual	M10046	-	-	-	-	-	0.6	0.6	0.6	-	0.6	0.6	0.6
left power	M10047	-	-	-	-	-	1	1	1	-	1	1	1
right power	M10048	-	-	-	-	-	1	1	1	-	1	1	1
GLASS, REAR DOOR-ADJUST													
left	M10050	-	-	-	-	-	-	0.4	0.4	-	-	0.4	0.4
right	M10051	-	-	-	-	-	-	0.4	0.4	-	-	0.4	0.4
GLASS, REAR DOOR-REPLACE													
INC: Nec. lubrication and adjustments.													
left	M10055	-	-	-	-	-	-	1.2	1.2	-	-	1.2	1.2
right	M10056	-	-	-	-	-	-	1.2	1.2	-	-	1.2	1.2
SEAL, REAR DOOR WINDOW, ONE PIECE													
ADD:													
A - To Replace Each Additional													
INC: R&R of door glass.													
SEAL, REAR DOOR WINDOW BELTLINE- R&R OR REPLACE													
Inner	M10060	-	-	-	-	-	-	0.3	0.3	-	-	0.3	0.3
outer	M10061	-	-	-	-	-	-	0.3	0.3	-	-	0.3	0.3
CHANNEL, REAR DOOR WINDOW RUN-R&R OR REPLACE													
left													
front	M10065	-	-	-	-	-	-	0.5	0.5	-	-	0.5	0.5
rear	M10066	-	-	-	-	-	-	0.5	0.5	-	-	0.5	0.5
right													
front	M10067	-	-	-	-	-	-	0.5	0.5	-	-	0.5	0.5
rear	M10068	-	-	-	-	-	-	0.5	0.5	-	-	0.5	0.5
HANDLE, REAR DOOR WINDOW REGULATOR-REPLACE													
left	M10070	-	-	-	-	-	-	0.2	0.2	-	-	0.2	0.2
right	M10071	-	-	-	-	-	-	0.2	0.2	-	-	0.2	0.2
REGULATOR, REAR DOOR WINDOW-R&R OR REPLACE													
INC: D&C glass, prop in up position and transfer motor where nec.													
left manual	M10073	-	-	-	-	-	-	0.6	0.6	-	-	0.6	0.6
right manual	M10074	-	-	-	-	-	-	0.6	0.6	-	-	0.6	0.6

left power	M10075	-	-	-	-	-	-	-	1	1	-	-	1	1
right power	M10076	-	-	-	-	-	-	-	1	1	-	-	1	1
CHANNEL, REAR DOOR-REPLACE														
left	M10077	-	-	-	-	-	-	-	0.6	0.5	-	-	0.5	0.5
right	M10078	-	-	-	-	-	-	-	0.6	0.5	-	-	0.5	0.5
GLASS, QUARTER SLIDING-RESEAL														
left	M10079	-	-	-	-	-	-	-	-	0.5	-	-	-	-
right	M10080	-	-	-	-	-	-	-	-	0.5	-	-	-	-
GLASS, QUARTER SLIDING-REPLACE														
left	M10081	-	-	-	-	-	-	-	-	0.7	-	-	-	-
right	M10082	-	-	-	-	-	-	-	-	0.7	-	-	-	-
FILLER, QUARTER GLASS SCREEN-REPLACE														
left	M10083	-	-	-	-	-	-	-	-	0.4	-	-	-	-
right	M10084	-	-	-	-	-	-	-	-	0.4	-	-	-	-
GLASS, QUARTER, SLANT BACK-RESEAL/REPLACE	m10085	-	-	-	-	-	-	-	-	-	-	-	-	0.5
GLASS, BACK WINDOW-RESEAL	M10090	-	-	-	-	-	-	0.5	0.5	-	-	0.5	-	-
GLASS, BACK WINDOW-REPLACE	M10091	-	-	-	-	-	-	1	1	-	-	1	-	-
GLASS, BACK WINDOW SLIDING-RESEAL	M10092	-	-	-	-	-	-	0.5	0.5	-	-	0.5	-	-
GLASS, BACK WINDOW SLIDING-REPLACE	M10093	-	-	-	-	-	-	1	1	-	-	1	-	-
INC: R&R rubber seal and water test.														
GLASS, LIFTGATE-REPLACE	M10095	-	-	-	-	-	-	-	-	0.4	-	-	-	-
SUPPORT, LIFTGATE GLASS (GAS TUBE)-REPLACE														
left	M10096	-	-	-	-	-	-	-	-	0.2	-	-	-	-
right	M10097	-	-	-	-	-	-	-	-	0.2	-	-	-	-
both	M10098	-	-	-	-	-	-	-	-	0.3	-	-	-	-
WEATHER STRIP, LIFTGATE WINDOW INNER SEALING-R&R OR REPLACE	M10099	-	-	-	-	-	-	-	-	0.5	-	-	-	-
WEATHER STRIP, LIFTGATE WINDOW OUTER SEALING-R&R OR REPLACE	M10100	-	-	-	-	-	-	-	-	0.3	-	-	-	-
GLASS, VERTICAL DOOR STATIONARY-RESEAL														
left	M10105	-	-	-	-	-	-	-	-	0.5	-	-	-	-
right	M10106	-	-	-	-	-	-	-	-	0.5	-	-	-	-
GLASS, VERTICAL DOOR STATIONARY-REPLACE														
left	M10107	-	-	-	-	-	-	-	-	0.5	-	-	-	-
right	M10108	-	-	-	-	-	-	-	-	0.5	-	-	-	-
GLASS, SLANT DOOR-RESEAL/REPLACE	m10109	-	-	-	-	-	-	-	-	-	-	-	-	0.8
GLASS, BACK OPERA-R&R OR REPLACE														
left	M10110	-	-	-	-	-	-	-	-	0.7	-	-	-	-
right	M10111	-	-	-	-	-	-	-	-	0.7	-	-	-	-
DOOR ASSEMBLY, FRONT-ADJUST														
left	M10115	-	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
right	M10116	-	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
HINGE, FRONT DOOR (BOLT ON)-REPLACE														
left upper	M10117	-	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5

	right upper	M10118	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5
	left lower	M10119	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4
	right lower	M10120	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4
ADD:															
A - Repaint			-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
STRAP, FRONT DOOR HOLD OPEN-REPLACE															
	left	M10125	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	right	M10126	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
HANDLE, FRONT DOOR OUTSIDE-REPLACE															
	left	M10130	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7	0.7
	right	M10131	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7	0.7
CYLINDER, FRONT DOOR LOCK-R&R OR REPLACE															
	left	M10132	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7	0.7
	right	M10133	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7	0.7
STRIKER, FRONT DOOR LOCK-REPLACE															
	left	M10134	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	right	M10135	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
LATCH, FRONT DOOR-R&R OR REPLACE															
	left	M10136	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8
	right	M10137	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8
HANDLE, INTERIOR, FRONT DOOR-R&R OR REPLACE															
	left	M10138	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	right	M10139	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
GUARD, STRIKER-REPLACE															
	each	M10140	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
KNOB, FRONT DOOR INSIDE LOCKING-REPLACE															
	left	M10141	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	right	M10142	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
ROD, FRONT DOOR INSIDE LOCKING-R&R OR REPLACE															
	left	M10145	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5
	right	M10146	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5
ROD, FRONT DOOR OUTSIDE HANDLE TO LATCH-REPLACE															
	left	M10147	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5
	right	M10148	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5
ROD, FRONT DOOR INSIDE HANDLE TO LATCH-REPLACE															
	left	M10149	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5
	right	M10150	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5
DOOR ASSEMBLY, REAR-ADJUST															
	left	M10155	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5	0.5
	right	M10156	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5	0.5
HINGE, REAR DOOR (BOLT ON)-REPLACE															
	left upper	M10157	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5	0.5
	right upper	M10158	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5	0.5
	left lower	M10159	-	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4	0.4

	right	lower	M10160	-	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4
ADD:															
A - Repaint				-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
HANDLE, REAR DOOR OUTSIDE-REPLACE															
	left		M10165	-	-	-	-	-	-	0.7	0.7	0.7	-	0.7	0.7
	right		M10166	-	-	-	-	-	-	0.7	0.7	0.7	-	0.7	0.7
STRIKER, REAR DOOR LOCK-REPLACE															
	left		M10167	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5
	right		M10168	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5
LATCH, REAR DOOR-R&R OR REPLACE															
	left		M10169	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5
	right		M10170	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5
HANDLE, INTERIOR, REAR DOOR-R&R OR REPLACE															
	left		M10171	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
	right		M10172	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
HANDLE, SLANT DOOR-R&R OR REPLACE			m10173	-	-	-	-	-	-	-	-	-	-	-	0.5
LATCH, SLANT DOOR-R&R OR REPLACE			m10174	-	-	-	-	-	-	-	-	-	-	-	0.5
DOOR ASSY, SLANT-ADJUST			m10175	-	-	-	-	-	-	-	-	-	-	-	0.8
HINGE/TORSION ASSY-R&R/REPLACE			m10179	-	-	-	-	-	-	-	-	-	-	-	2
KNOB & CABLE, REAR DOOR INSIDE LOCKING-R&R OR REPLACE															
	left		M10177	-	-	-	-	-	-	0.7	0.7	0.7	-	0.7	0.7
	right		M10178	-	-	-	-	-	-	0.7	0.7	0.7	-	0.7	0.7
ROD, REAR DOOR INSIDE HANDLE TO LATCH-R&R OR REPLACE															
	left		M10180	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5
	right		M10181	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5
STRAP, REAR DOOR HOLD OPEN-R&R OR REPLACE															
	left		M10185	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
	right		M10186	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
ROD, OUTSIDE HANDLE TO LATCH- REPLACE															
	left		M10187	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5
	right		M10188	-	-	-	-	-	-	0.5	0.5	0.5	-	0.5	0.5
TAILGATE ASSEMBLY-ALIGN			M10194	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-
HINGE, TAILGATE-REPLACE															-
	left		M10196	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	-
	right		M10197	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	-
ADD:															-
A - Repaint				-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-
CHAINS, TAILGATE-REPLACE															-
	left		M10198	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-
	right		M10199	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-
HANDLE, LIFTGATE OUTSIDE-REPLACE			M10200	-	-	-	-	-	-	-	0.3	-	-	-	-
CYLINDER, LIFTGATE LOCK-R&R OR REPLACE			M10201	-	-	-	-	-	-	-	0.4	-	-	-	-
HANDLE, LIFTGATE INSIDE-REPLACE			M10202	-	-	-	-	-	-	-	0.3	-	-	-	-
DOOR ASSEMBLY, VERTICAL-ADJUST															

	left	M10210	-	-	-	-	-	-	-	0.5	-	-	-	-
	right	M10211	-	-	-	-	-	-	-	0.5	-	-	-	-
HINGE, VERTICAL DOOR-REPLACE														
	left	M10215	-	-	-	-	-	-	-	0.6	-	-	-	-
	right	M10216	-	-	-	-	-	-	-	0.6	-	-	-	-
HANDLE, VERTICAL DOOR-REPLACE														
	(outer) left	M10217	-	-	-	-	-	-	-	0.5	-	-	-	-
	(inner/outer) right	M10218	-	-	-	-	-	-	-	0.7	-	-	-	-
CYLINDER, VERTICAL DOOR LOCK-R&R OR REPLACE														
STRIKER, VERTICAL DOOR LOCK-REPLACE														
	lh upper	M10220	-	-	-	-	-	-	-	0.3	-	-	-	-
	rh upper	M10221	-	-	-	-	-	-	-	0.3	-	-	-	-
	lh lower	M10222	-	-	-	-	-	-	-	0.3	-	-	-	-
	rh lower	M10223	-	-	-	-	-	-	-	0.3	-	-	-	-
LATCH, VERTICAL DOOR-R&R OR REPLACE														
	lh upper	M10224	-	-	-	-	-	-	-	0.5	-	-	-	-
	rh upper	M10225	-	-	-	-	-	-	-	0.5	-	-	-	-
	lh lower	M10226	-	-	-	-	-	-	-	0.5	-	-	-	-
	rh lower	M10227	-	-	-	-	-	-	-	0.5	-	-	-	-
BRACKET, TAILGATE CHAIN-REPLACE														
	left	M10230	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-
	right	M10231	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-
ROD, VERTICAL DOOR LOCK LATCH-REPLACE														
	lh upper	M10232	-	-	-	-	-	-	-	0.5	-	-	-	-
	rh upper	M10233	-	-	-	-	-	-	-	0.5	-	-	-	-
	lh lower	M10234	-	-	-	-	-	-	-	0.5	-	-	-	-
	rh lower	M10235	-	-	-	-	-	-	-	0.5	-	-	-	-
HOLD OPEN ASSEMBLY, DOOR, VERTICAL-REPLACE														
WEATHERSTRIP-ALIGN OR REPLACE														
	windshield glass	M10240	-	-	-	-	-	1	1	1	1	1	1	1
front door														
	left	M10245	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7
	right	M10246	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7
front door body														
	left	M10250	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
	right	M10251	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
rear door														
	left	M10255	-	-	-	-	-	-	0.7	0.7	0.5	-	0.7	0.7
	right	M10256	-	-	-	-	-	-	0.7	0.7	0.5	-	0.7	0.7
rear door body														
	left	M10260	-	-	-	-	-	-	0.5	0.5	0.3	-	0.5	0.5
	right	M10261	-	-	-	-	-	-	0.5	0.5	0.3	-	0.5	0.5
	(side) tailgate	M10262	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	(bottom) tailgate	M10263	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3

[illegible]

[illegible]

[illegible]

LEFT TRIM	M10416	-	-	-	-	-	-	-	-	-	-	-	0.3	-
RIGHT TRIM	M10417	-	-	-	-	-	-	-	-	-	-	-	0.3	-
CENTER TRIM	M10418	-	-	-	-	-	-	-	-	-	-	-	0.4	-
TOP	M10419	-	-	-	-	-	-	-	-	-	-	-	0.6	-
CONSOLE-FRONT-REPLACE	M10413	-	-	-	-	-	1.2	1.2	1.2	1.2	1.2	1.2	1.2	-
ADD: 2004 Model Year and Above		-	-	-	-	-	-	1.5	1.5	-	-	1.5	1.5	-
DRINK TRAY-REPLACE	M10415	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2	-
ASHTRAY-REPLACE	M10420	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2	-
GLOVE BOX-REPLACE	M10425	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2	-
BEZEL, HVAC/RADIO-REPLACE	M10426	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4	-
BEZEL, MASTER SWITCH, POWER WINDOW-REPLACE	M10427	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
BEZEL, DOOR LOCK SWITCH-REPLACE	M10428	-	-	-	-	-	-	0.3	0.3	-	-	0.3	0.3	0.3
BEZEL, SHIFTER-REPLACE	M10430	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
BEZEL, PARKING BRAKE-REPLACE	M10433	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
CONSOLE, REAR-REPLACE	M10435	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
PANEL, I/P CLOSEOUT-REPLACE														
CENTER	M10437	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
LEFT	M10438	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
RIGHT	M10439	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	0.5
PANEL, FRONT KICK, OUTER-REPLACE														
LEFT HAND	M10445	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
RIGHT HAND	M10446	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
PANEL, FRONT KICK, inner-REPLACE														
LEFT HAND	M10450	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6
RIGHT HAND	M10451	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6
PANEL, SHIFTER/BRAKE-REPLACE	M10455	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6
PANEL, CENTER KICK, OUTER-REPLACE														
LEFT HAND	M10457	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4
RIGHT HAND	M10458	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4
PANEL, REAR KICK, OUTER-REPLACE														
LEFT HAND	M10460	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3	0.3
RIGHT HAND	M10461	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3	0.3
PLATES, DOOR SCUFF-REPLACE														
FRONT														
LEFT	M10465	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
RIGHT	M10466	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
REAR														
LEFT	M10467	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3	0.3
RIGHT	M10468	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3	0.3
B-BEAM PANEL-REPLACE														
CENTER	M10470	-	-	-	-	-	-	0.3	0.3	-	-	-	-	-
B-PILLAR, UPPER-REPLACE														
LEFT HAND	M10471	-	-	-	-	-	-	0.5	0.5	-	-	-	-	-
RIGHT HAND	M10472	-	-	-	-	-	-	0.5	0.5	-	-	-	-	-

B-PILLAR, CENTER-REPLACE														
	LEFT HAND	M10473	-	-	-	-	-	-	0.3	0.3	-	-	-	-
	RIGHT HAND	M10474	-	-	-	-	-	-	0.3	0.3	-	-	-	-
B-PILLAR, LOWER-REPLACE														
	LEFT HAND	M10475	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
	RIGHT HAND	M10476	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
PANEL, HEADLINER-REPLACE														
	FRONT	M10480	-	-	-	-	-	1.2	1.2	1.2	-	1.2	-	-
ADD: 2004 Model Year and Above			-	-	-	-	-	-	0.6	0.6	-	0.6	-	-
	CENTER	M10481	-	-	-	-	-	-	-	1	-	-	-	-
	REAR	M10482	-	-	-	-	-	-	1.2	1.2	-	-	-	-
HANDLE, GRAB-REPLACE														
	FRONT													
	LEFT	M10485	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	RIGHT	M10486	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	REAR													
	LEFT	M10487	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
	RIGHT	M10488	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
WHEELHOUSE, LOWER-REPLACE														
	LEFT	M10490	-	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4
	RIGHT	M10491	-	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4
WHEELHOUSE, UPPER-REPLACE														
	LEFT	M10492	-	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4
	RIGHT	M10493	-	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4
WHEELHOUSE, CENTER-REPLACE														
	LEFT	M10494	-	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4
	RIGHT	M10495	-	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4
PANEL, REAR, LOWER, CENTER-REPLACE		M10500	-	-	-	-	-	1	1	1	1	1	1	1
PANEL, REAR WINDOW TRIM-REPLACE		M10505	-	-	-	-	-	0.8	0.8	-	-	0.8	-	-
PANEL, AMP COVER-REPLACE														
	LEFT	M10506	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
	RIGHT	M10507	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3
C-PILLAR TRIM-REPLACE														
	C-BEAM CENTER	M10514	-	-	-	-	-	-	-	0.3	-	-	-	-
	UPPER													
	LEFT	M10510	-	-	-	-	-	-	-	0.5	-	-	-	-
	RIGHT	M10511	-	-	-	-	-	-	-	0.5	-	-	-	-
	LOWER													
	LEFT	M10512	-	-	-	-	-	-	-	0.4	-	-	-	-
	RIGHT	M10513	-	-	-	-	-	-	-	0.4	-	-	-	-
PANEL, UPPER TRIM, REAR-REPLACE														
	LEFT	M10520	-	-	-	-	-	-	-	0.3	-	-	-	-
	RIGHT	M10521	-	-	-	-	-	-	-	0.3	-	-	-	-
PANEL, CLOSEOUT, VERTICAL DOORS-REPLACE		M10522	-	-	-	-	-	-	-	0.2	-	-	-	-

[illegible]

	REPLACE	M10609	-	-	-	-	-	-	5	5	5	-	5	5
	REPAIR	M10612	-	-	-	-	-	-	3	3	3	-	3	3
COWL														
	REPLACE	M10615	-	-	-	-	-	5	5	5	5	5	5	5
	REPAIR	M10618	-	-	-	-	-	2.5	2.5	2.5	2.5	2.5	2.5	2.5
FENDERWELL, REAR, TOP														
POLICY: A														
	REPLACE	M10620	-	-	-	-	-	5	6.5	10	5	5	5	9
	REPAIR	M10625	-	-	-	-	-	3	3	3	3	3	3	3
PANEL, body SIDE														
	REPLACE	M10630	-	-	-	-	-	6	6	6	6	6	6	6
	REPAIR	M10633	-	-	-	-	-	5	5	5	5	5	5	5
FENDERWELL, REAR, OUTER-REPLACE														
POLICY: A														
	left hand	M10636	-	-	-	-	-	4.5	6	7	5	4.5	4.5	7
	right hand	M10637	-	-	-	-	-	5	6.5	7.5	5.5	5	5	7.5
FENDERWELL, REAR, OUTER-REPAIR														
	left hand	M10640	-	-	-	-	-	4	4.5	4.5	4	4	4	4.5
	right hand	M10641	-	-	-	-	-	4.5	5	5	4.5	4.5	4.5	5
SIDE PANEL, WAGON REAR														
	repair	M10643	-	-	-	-	-	-	-	3	-	-	-	-
CAB, REAR														
POLICY: A														
	REPLACE	M10646	-	-	-	-	-	7	7	-	-	7	-	-
	REPAIR	M10648	-	-	-	-	-	3.5	3.5	-	-	3.5	-	-
CARGO FLOOR-REPAIR														
DOOR, VERTICAL INTERIOR-REPLACE														
	left hand	M10655	-	-	-	-	-	-	-	1.5	-	-	-	-
	right hand	M10656	-	-	-	-	-	-	-	1.5	-	-	-	-
DOOR, VERTICAL INTERIOR-REPAIR														
	left hand	M10657	-	-	-	-	-	-	-	1	-	-	-	-
	right hand	M10658	-	-	-	-	-	-	-	1	-	-	-	-
DOOR, VERTICAL EXTERIOR-REPLACE														
	left hand	M10660	-	-	-	-	-	-	-	2.2	-	-	-	-
	right hand	M10661	-	-	-	-	-	-	-	2.2	-	-	-	-
DOOR, VERTICAL EXTERIOR-REPAIR														
	left hand	M10665	-	-	-	-	-	-	-	1	-	-	-	-
	right hand	M10666	-	-	-	-	-	-	-	1	-	-	-	-
TAILGATE-REPLACE														
POLICY: A														-
TAILGATE-REPAIR														
BRUSHGUARD-REPLACE														
BUMPER, FRONT-REPLACE														
POLICY: A														
		M10669	-	-	-	-	-	1	1	1	1	1	1	-
		K9230	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
		K9050	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5

BUMPER, FRONT-REPAIR	M10671	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8
BUMPER, REAR-REPLACE	K9170	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8
POLICY: A													
ADD:													
A - Trailer Hitch		-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
BUMPER, REAR-REPAIR	M10673	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8
LOAD BARRIER-REPLACE	M10674	-	-	-	-	-	-	-	0.3	-	-	-	0.3
LOAD BARRIER-REPAIR	M10675	-	-	-	-	-	-	-	0.5	-	-	-	0.5
ROCKER PANEL PROTECTION-REPLACE	M10676	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8
ROCKER PANEL PROTECTION-REPAIR	M10677	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
WINDSHIELD, HINGE-REPLACE	M10678	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
WEATHER CAP-REPLACE	C3190	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
WEATHER CAP-REPAIR	M10680	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
CARGO NET-REPLACE	M10681	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	-
WINDSHIELD, FORMER ASSEMBLY-REPLACE	M10682	-	-	-	-	-	-	-	-	0.4	-	0.4	-
"B" BAR ASSEMBLY-REPLACE	M10683	-	-	-	-	-	2.5	2.5	2.5	-	2.5	-	2.5
"C" BAR ASSEMBLY-REPLACE	M10684	-	-	-	-	-	-	2.5	2.5	2.5	-	2.5	2.5
BRACKET, TONNEAU-REPLACE	M10685	-	-	-	-	-	-	0.3	-	0.3	-	0.3	-
COVER, AIR EXHAUSTER, VENT-REPLACE													
left hand	M10686	-	-	-	-	-	0.2	0.2	0.2	-	0.2	-	-
right hand	M10687	-	-	-	-	-	0.2	0.2	0.2	-	0.2	-	-
LIFTGATE ASSEMBLY-REPLACE	M10690	-	-	-	-	-	-	-	1.6	-	-	-	-
LIFTGATE ASSEMBLY-REPAIR	M10691	-	-	-	-	-	-	-	1	-	-	-	-
SKID PLATE, W OR W/O WINCH-REPLACE	M10693	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
POLICY: A													
SOFT TOP STRUCTURE-REPLACE													-
left hand rear	M10694	-	-	-	-	-	-	-	-	0.7	-	0.7	-
right hand rear	M10695	-	-	-	-	-	-	-	-	0.7	-	0.7	-
left hand side	M10696	-	-	-	-	-	-	-	-	0.9	-	0.9	-
right hand side	M10697	-	-	-	-	-	-	-	-	0.9	-	0.9	-
center front	M10698	-	-	-	-	-	-	-	-	1.2	-	1.2	-
center rear	M10699	-	-	-	-	-	-	-	-	1.2	-	1.2	-
COVER, SOFT TOP-REPLACE	M10700	-	-	-	-	-	-	-	-	0.5	-	0.5	-
POLICY: A													-
COVER, SOFT TOP-REPAIR	M10701	-	-	-	-	-	-	-	-	1	-	1	-
COVER, KIT, TONNEAU-REPLACE	M10702	-	-	-	-	-	-	0.2	-	0.2	-	0.2	-
POLICY: A													-
COVER, TONNEAU-REPAIR	M10703	-	-	-	-	-	-	1	-	1	-	1	-
WINDOW ASSY, BACK, SOFT TOP-REPLACE	M10704	-	-	-	-	-	-	-	-	-	-	0.2	-
RETAINER, SOFT TOP VELCRO-REPLACE													-
one	M10705	-	-	-	-	-	-	-	-	0.3	-	0.3	-
all	M10706	-	-	-	-	-	-	-	-	0.5	-	0.5	-
RETAINER, TONNEAU COVER VELCRO-REPLACE													-
one	M10707	-	-	-	-	-	-	0.3	-	0.3	-	0.3	-

	all	M10708	-	-	-	-	-	-	0.5	-	0.5	-	0.5	-
SOFT TOP BOLSTER COVER-REPLACE														
	one	M10709	-	-	-	-	-	-	-	-	0.3	-	0.3	-
	all	M10710	-	-	-	-	-	-	-	-	0.5	-	0.5	-
AIR BOX-REPLACE			M10715	-	-	-	-	-	4	4	4	4	4	4
AIR BOX-REPAIR			M10716	-	-	-	-	-	2.5	2.5	2.5	2.5	2.5	2.5
SCOOP, AIR INTAKE-REPLACE			M10717	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3
HOOD ASSEMBLY														
POLICY: A														
INC: Primer and paint														
	REPLACE	M10720	-	-	-	-	-	-	11.5	11.5	11.5	11.5	11.5	11.5
	REPAIR	M10721	-	-	-	-	-	-	5	5	5	5	5	5
HOOD-ALIGN			M10722	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3
GRILLE/SCREEN, UPPER, HOOD-REPLACE			M10723	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
HOLDDOWN, BRACKET/STOP, HOOD-REPLACE														
	left hand	M10725	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3
	right hand	M10726	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3
CENTER BRACKET, HOOD-REPLACE			M10730	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3
HOLDDOWN STRAP, HOOD-REPLACE														
	left hand	M10731	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
	right hand	M10732	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
HINGE, HOOD-REPLACE														
	upper													
	left hand	M10735	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
	right hand	M10736	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
2006 MODEL YEAR AND ABOVE			M10734	-	-	-	-	-	-	-	0.3	-	-	0.3
	lower													
	left hand	M10737	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
	right hand	M10738	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
2006 MODEL YEAR AND ABOVE			M10739	-	-	-	-	-	-	-	0.3	-	-	0.3
RETAINER PLATE, HOOD-REPLACE														
	left hand	M10740	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
	right hand	M10741	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4
BRACKET, HOOD, LOCK-REPLACE			M10745	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3
CABLE, HOOD, LOCK-REPLACE			M10746	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5
SCREEN, HOOD, GRILLE, LOWER-REPLACE			M10747	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3
CENTERING BLOCK, HOOD-REPLACE			M10748	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2
SEAL, RADIATOR TO HOOD-REPLACE			M10749	-	-	0.3	-	-	-	-	-	-	-	-
SEAL, RIGHT HAND, HOOD-REPLACE			M10750	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2
SEAL AT AIR BOX, BODY-REPLACE			M10751	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2
SEAL, CENTER HOOD AT GRILLE-REPLACE			M10752	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2
SPASH SHIELD ASSEMBLY-REPLACE														
	left hand	M10753	-	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6
	right hand													

one-piece	M10754	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
upper	M10755	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
lower	M10756	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
BRACKET, HOOD, PROP ROD-REPLACE	M10757	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
PROP ROD ASSEMBLY, HOOD-REPLACE	M10760	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
BRACKET ASSEMBLY AND "A" BEAM, HOOD LOCK-REPLACE	M10762	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
ARM, MIRROR, EXTERIOR ONLY-REPLACE	M10763	-	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
HEAD, MIRROR, EXTERIOR ONLY-REPLACE	M10764	-	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
MIRROR, EXTERIOR, REARVIEW-REPLACE														
left hand	M10765	-	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
right hand	M10766	-	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
MIRROR, EXTERIOR, REARVIEW POWER-REPLACE														
POLICY: A		-	-	-	-	-	-							
left hand	M10767	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
right hand	M10768	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
GLASS, MIRROR, EXTERIOR ONLY-REPLACE														
left hand	M10769	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
right hand	M10770	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
COVER, ENGINE-REPLACE	M10771	-	-	-	-	-	-	1	1	1	1	1	1	1
ADD: 2004 Model Year and Above		-	-	-	-	-	-	-	1.5	1.5	-	1.5	1.5	-
FLEXIBLE LATCH AND HOLDDOWN, ENGINE COVER-REPLACE	M10772	-	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7
BRACKET, AIR CLEANER-REPLACE	M10773							0.4	0.4	0.4	0.4	0.4	0.4	0.4
DRIVELINE PROTECTION-REPLACE														
POLICY: A														
rear	M10777	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
front	M10778	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
middle	M10779	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
side bracket	M10780	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
aux. fuel tank	M10781	-	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
t-case skid plate	M10782	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
HITCH ASSEMBLY, TRAILER TOWING-REPLACE	M10785	-	-	-	-	-	-	1	1	1	1	1	1	1
POLICY: A														
MOUNTING BRACKET, TRAILER TOWING HITCH-REPLACE														
POLICY: A														
left hand	M10790	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
right hand	M10791	-	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	M10792	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
DECALS-REPLACE	M10795	-	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
ADD:														
A - To Apply Clear Protective		-	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
PANEL, SHELL, SLANT BACK-REPLACE														
left	m10940	-	-	-	-	-	-	-	-	-	-	-	-	0.3
right	m10941	-	-	-	-	-	-	-	-	-	-	-	-	0.3
PANEL, HINGE COVER, SLANT BACK-REPLACE														

[illegible]

	SPOT	M10825	-	-	-	-	-	1	1	1	1	1	1	1	1
	COMPLETE	M10826	-	-	-	-	-	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5
FOOTWELL, COVER ASSY-PAINT															
	SPOT	M10827	-	-	-	-	-	1	-	-	-	1	-	-	-
	COMPLETE	M10829	-	-	-	-	-	1.5	-	-	-	1.5	-	-	-
FENDERWELL, REAR, INNER-PAINT															
	spot	M10830	-	-	-	-	-	1	1	1	1	1	1	1	1
	COMPLETE	M10837	-	-	-	-	-	2	2	2	2	2	2	2	2
FENDERWELL, rear TOP-PAINT															
	SPOT	M10840	-	-	-	-	-	1	1	1	1	1	1	1	1
	COMPLETE	M10842	-	-	-	-	-	2	2	2.5	2.5	2	2.5	2.5	2.5
FIXED DOOR, INNER PANEL-PAINT															
	SPOT	M10845	-	-	-	-	-	1	-	-	-	1	-	-	-
	COMPLETE	M10847	-	-	-	-	-	1.5	-	-	-	1.5	-	-	-
COWL, FRONT-PAINT															
	SPOT	M10848	-	-	-	-	-	1	1	1	1	1	1	1	1
	COMPLETE	M10849	-	-	-	-	-	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5
DOOR, FRONT-PAINT															
	SPOT	M10850	-	-	-	-	-	1	1	1	1	1	1	1	1
	COMPLETE	M10851	-	-	-	-	-	3	3	3	3	3	3	3	3
BODY SIDE PANEL-PAINT															
	SPOT	M10852	-	-	-	-	-	1	1	1	1	1	1	1	1
	COMPLETE	M10853	-	-	-	-	-	2	2	2	2	2	2	2	2
B-PILLAR-PAINT															
		M10855	-	-	-	-	-	1	1	1	1	1	1	1	1
DOOR, REAR-PAINT															
	SPOT	M10856	-	-	-	-	-	1	1	1	1	1	1	1	1
	COMPLETE	M10857	-	-	-	-	-	3	3	3	3	3	3	3	3
C-PILLAR-PAINT															
		M10858	-	-	-	-	-	1	1	1	1	1	1	1	1
FENDERWELL, REAR, OUTER-PAINT															
	SPOT	M10859	-	-	-	-	-	1	1	1	1	1	1	1	1
	COMPLETE	M10860	-	-	-	-	-	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5
SIDE PANEL, WAGON REAR															
	SPOT	M10861	-	-	-	-	-	-	-	1	-	-	-	-	-
	COMPLETE	M10862	-	-	-	-	-	-	-	2.5	-	-	-	-	-
CAB, REAR-PAINT															
	SPOT	M10877	-	-	-	-	-	-	1	-	-	1	-	-	-
	COMPLETE	M10878	-	-	-	-	-	-	2.5	-	-	2.5	-	-	-
WAGON, REAR-PAINT															
	SPOT	M10879	-	-	-	-	-	-	-	1	-	-	-	-	-
	COMPLETE	M10880	-	-	-	-	-	-	-	2	-	-	-	-	-
DOOR, WAGON REAR, EXTERIOR-PAINT															
	SPOT	M10881	-	-	-	-	-	-	-	1	-	-	-	-	-
	COMPLETE	M10882	-	-	-	-	-	-	-	2	-	-	-	-	-
DOOR, WAGON REAR, INTERIOR-PAINT															

	SPOT	M10885	-	-	-	-	-	-	-	1	-	-	-	-
	COMPLETE	M10886	-	-	-	-	-	-	-	2	-	-	-	-
TAILGATE, EXTERIOR-PAINT														
	SPOT	M10889	-	-	-	-	-	1	1	1	1	1	1	-
	COMPLETE	M10890	-	-	-	-	-	2	2	2	2	2	2	-
TAILGATE, INTERIOR-PAINT														
	SPOT	M10891	-	-	-	-	-	1	1	1	1	1	1	-
	COMPLETE	M10892	-	-	-	-	-	2	2	2	2	2	2	-
BUMPER, REAR-PAINT														
INC: SHACKLES														
	SPOT	M10893	-	-	-	-	-	1	1	1	1	1	1	1
	COMPLETE	M10894	-	-	-	-	-	2.5	2.5	2.5	2.5	2.5	2.5	2.5
TRAILER HITCH-PAINT														
	COMPLETE	M10895	-	-	-	-	-	1.5	1.5	1.5	1.5	1.5	1.5	1.5
SPARE TIRE CARRIER-PAINT														
	SPOT													
	BED-MOUNTED	M10897	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7
	SWING-AWAY	M10898	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7
	COMPLETE	M10899	-	-	-	-	-	1.5	1.5	1.5	1.5	1.5	1.5	1.5
LOAD BARRIER-PAINT														
	SPOT	M10900	-	-	-	-	-	-	-	1	-	-	-	-
	COMPLETE	M10901	-	-	-	-	-	-	-	2	-	-	-	-
ROCKER PANEL PROTECTION-PAINT														
	SPOT	M10902	-	-	-	-	-	1	1	1	1	1	1	1
	COMPLETE	M10903	-	-	-	-	-	1.5	1.5	1.5	1.5	1.5	1.5	1.5
LIGHT BAR, CLEARANCE, REAR-PAINT														
	COMPLETE	M10906	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
RACK, LUGGAGE-PAINT														
	SPOT	M10910	-	-	-	-	-	0.7	0.7	0.7	-	0.7	-	0.7
	COMPLETE	M10911	-	-	-	-	-	1.5	1.5	1.5	-	1.5	-	1.5
HINGE, DOOR, SIDE-PAINT														
		M10915	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7
WHEELS-PAINT														
	SPOT	M10918	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
	COMPLETE	M10919	-	-	-	-	-	1	1	1	1	1	1	1
PANEL, DOOR CLOSEOUT-PAINT														
		M10922	-	-	-	-	-	-	-	-	-	-	0.8	-
HINGE, WINDSHIELD-PAINT														
		M10924	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
WEATHER CAP, ENGINE AIR INTAKE-PAINT														
		M10926	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8
AIR BOX, HVAC AND ENGINE-PAINT														
		M10927	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8
SCOOP, AIR INTAKE-PAINT														
		M10928	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
COVER, AIR EXHAUSTER VENT-PAINT														
		M10929	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8
UNDERCARRIAGE-PAINT														
		M10932	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
GUARD, PLATE, CTIS-PAINT														
INC: BRACKET														
	ONE	M10934	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3

EACH ADDITIONAL	M10935	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
-----------------	--------	---	---	---	---	---	-----	-----	-----	-----	-----	-----	-----

HUMMER H1							HVAC						
OPERATION DESCRIPTION	OPERATION NUMBER	ENGINE					MODEL						
		X	Y	Z/F	D/L	P	82	83 and 56	84 and 57	85	89 and 55	90 and 58	91 and 59
SOME LABOR OPERATIONS IN THIS SECTION HAVE AN ADD CONDITION "TO CLEAN PARTS ON VEHICLES OVER 30,000 MILES IF NEC." WHEN CLAIMING THIS "ADD," THE PARTICULAR LABOR OPERATION INVOLVED MUST BE CITED AS Y-TIME (ADD TIME).													
SWITCH, BLOWER MOTOR-REPLACE													
heater	N11000	0.8	-	-	-	-	-	-	-	-	-	-	-
auxiliary heater/ac	N11001	0.3	0.3	0.3	0.3	0.8	-	-	-	-	-	-	-
ADD:													
A - 2004 Model Year		-	-	0.5	-	-	-	-	-	-	-	-	-
CONTROL ASSEMBLY-REPLACE													
a/c	N11005	1.1	1.1	1.1	1.1	1.1	-	-	-	-	-	-	-
HARNESS, VACUUM ABOVE VIN 176477-REPLACE	N11006	-	1	1	-	2.5	-	-	-	-	-	-	-
ADD:													
A - 2004 Model Year		-	-	1.5	-	-	-	-	-	-	-	-	-
PUMP, a/c VACUUM-REPLACE	N11007	-	-	-	-	0.3	-	-	-	-	-	-	-
NOTE: See B2185 for Engine Vacuum Pump													
RESISTOR, BLOWER MOTOR-REPLACE													
a/c heater	N11010	0.3	0.3	0.3	0.3	0.8	-	-	-	-	-	-	-
ADD:													
A - 1996 Model Year or Prior		1.1	1.1	1.1	1.1	-	-	-	-	-	-	-	-
B - 2004 Model Year		-	-	0.5	-	-	-	-	-	-	-	-	-
RELAY-REPLACE													
blower motor	N11015	0.3	0.3	0.3	0.3	0.8	-	-	-	-	-	-	-
compressor	N11016	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
SWITCH, COMPRESSOR CUT-OFF-REPLACE	N11020	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
SWITCH, THERMOSTATIC CYCLING ABOVE VIN 176477-REPLACE	N11021	-	1.6	1.6	-	1.6	-	-	-	-	-	-	-
SWITCH, PRESSURE CYCLING-REPLACE	N11025	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
TUBE, BLOWER MOTOR COOLING-REPLACE	N11030	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
MOTOR AND/OR FAN, BLOWER-R&R OR REPLACE													
heater a/c	N11035	4.5	1.2	1.2	1.2	-	-	-	-	-	-	-	-
auxiliary a/c	N11036	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
heater a/c, above vin 176477	N11037	-	0.5	0.5	-	0.5	-	-	-	-	-	-	-
HOUSING, BLOWER MOTOR-REPLACE													
above vin 176477	N11040	-	1	1	-	1	-	-	-	-	-	-	-

below vin 176477	N11041	1.5	1.5	1.5	1.5	-	-	-	-	-	-	-	-	-
NOZZLE, DEFROSTER OUTLET-REPLACE														
right	N11045	1.2	1.2	1.2	1.2	0.3	-	-	-	-	-	-	-	-
left	N11046	2.6	2.6	2.6	2.6	0.3	-	-	-	-	-	-	-	-
DUCTING-REPLACE														
plenum	N11047	0.6	0.6	0.6	0.6	0.5	-	-	-	-	-	-	-	-
transition assembly	N11050	0.6	0.6	0.6	0.6	1.2	-	-	-	-	-	-	-	-
floor														
left	N11055	1.2	1.2	1.2	1.2	2	-	-	-	-	-	-	-	-
right, above vin 176477	N11056	-	0.5	0.5	-	1.2	-	-	-	-	-	-	-	-
right, below vin 176477	N11057	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-	-	-
defroster														
left	N11060	2.6	2.6	2.6	2.6	2.6	-	-	-	-	-	-	-	-
right	N11061	1.2	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
demister														
left	N11065	2.6	2.6	2.6	2.6	0.2	-	-	-	-	-	-	-	-
right	N11066	0.4	0.4	0.4	0.4	0.2	-	-	-	-	-	-	-	-
rear air														
left	N11070	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-	-
LOUVERS, AIR-REPLACE														
driver floor	N11072	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
dash left	N11073	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
console right	N11074	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
console left	N11075	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
demister right side glass	N11076	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
demister left side glass	N11077	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
aux front	N11078	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
aux rear	N11079	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
aux inlet	N11080	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
DIVERTER, ASSEMBLY-REPLACE	N11082	1	1	1	1	-	-	-	-	-	-	-	-	-
MOTOR, DOOR, ACTUATOR, ABOVE VIN 176477-REPLACE	N11083	-	0.5	0.5	-	1.2	-	-	-	-	-	-	-	-
ACTUATOR MODE DOOR-REPLACE														
air inlet (recirculation)	N11085	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-	-
TEMPERATURE DOOR	N11087	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-	-
CASE, EVAPORATOR-REPAIR (DRAIN HOSE)	N11090	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-
VALVE, COOLANT-REPLACE														
NOTE: Also referred to as hot water valve located in engine compartment.	N11095	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
SOLENOID, COOLANT VALVE-REPLACE	N11096	-	0.2	0.2	0.2	-	-	-	-	-	-	-	-	-
HOSES, HEATER-REPLACE														
inlet	N11100	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
outlet	N11101	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
all hoses	N11102	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-	-

Heater core, 2003 Model year and above		N11106	-	-	0.2	-	3.5	-	-	-	-	-	-	-
HOSES, AUXILIARY HEATER-REPLACE														
inlet		N11103	0.8	0.8	0.8	0.8	1.8	-	-	-	-	-	-	-
outlet		N11104	0.8	0.8	0.8	0.8	1.8	-	-	-	-	-	-	-
both		N11105	1	1	1	1	2	-	-	-	-	-	-	-
ADD:														
A - 2004 Model Year			-	-	1	-	-	-	-	-	-	-	-	-
A/C SYSTEM-LEAK TEST DISCHARGED SYSTEM			N11111	0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-
NOTE: This labor operation to be used when necessary to partially charge (1 lb. max) the A/C system to locate a leak.														
CORE, SCHRADER VALVE-REPLACE			N11120	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-
ADD:														
A - Recover/Recharge A/C System				0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-
SEALS, REFRIGERANT "O" RING-REPLACE														
compressor manifold		N11130	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
condenser inlet pipe		N11131	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
condenser outlet pipe		N11132	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
evaporator inlet		N11133	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
evaporator outlet		N11134	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
receiver/dryer		N11135	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
pressure switch		N11136	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
aux a/c inlet, front		N11137	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
aux a/c outlet, front		N11138	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
aux a/c inlet, rear		N11139	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
aux a/c outlet, rear		N11140	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
ADD:														
A - Recover/Recharge A/C System				0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-
GASKET, EVAPORATOR OUTLET, ABOVE VIN 176477-REPLACE			N11141	-	0.2	0.2	-	0.2	-	-	-	-	-	-
ADD:														
A - Recover/Recharge A/C System				-	0.7	0.7	-	0.7	-	-	-	-	-	-
HOSES AND/OR LINES, REFRIGERANT-REPLACE														
condenser to receiver dryer		N11145	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
receiver dryer to evaporator		N11146	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
compressor suction/discharge		N11147	0.6	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-
compressor suction		N11148	-	0.4	0.4	-	0.4	-	-	-	-	-	-	-
compressor discharge		N11149	-	0.4	0.4	-	0.4	-	-	-	-	-	-	-
ADD:														
A - Recover/Recharge A/C System				0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-
HOSES AND/OR LINES, REFRIGERANT (AUX A/C)-REPLACE														
high pressure		N11150	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
low pressure		N11151	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
ADD:														

A - 2004/2006 Model Year		-	-	1	-	1	-	-	-	-	-	-	-
block and a/c suction above vin 176477	N11152	-	0.4	0.4	-	0.4	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
VALVE, EXPANSION MAIN UNIT, ABOVE VIN 176477-REPLACE	N11153	-	0.3	0.3	-	0.3	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		-	0.7	0.7	-	0.7	-	-	-	-	-	-	-
CONDENSER-REPLACE	N11155	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
VALVE, EXPANSION AUX. UNIT-REPLACE	N11156	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
RECEIVER/DRYER ASSEMBLY-REPLACE	N11157	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
HOSE, EVAPORATION DRAIN-REPLACE													
main unit	N11158	0.2	0.2	0.2	0.2	0.2	-	-	-	-	-	-	-
aux unit	N11159	0.5	0.5	0.5	0.5	0.5	-	-	-	-	-	-	-
MAIN A/C-HEAT ASSEMBLY-REPLACE													
POLICY: A													
main unit	N11165	2.3	2.3	2.3	2.3	-	-	-	-	-	-	-	-
main unit above vin 176477	N11166	-	1.6	1.6	-	3.1	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
CASE HALF, MAIN HVAC ABOVE VIN 176477-REPAIR/REPLACE	N11167	-	1.9	1.9	-	3.4	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		-	0.7	0.7	-	0.7	-	-	-	-	-	-	-
HOUSING, AIR INTAKE, UPPER AND/OR LOWER, ABOVE VIN 176477-REPLACE	N11169	-	1	1	-	3.4	-	-	-	-	-	-	-
CORE, EVAPORATOR-REPLACE													
INC: Drain and Refill Coolant													
main unit above vin 176477	N11168	-	3.2	3.2	-	4.2	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
aux unit/with heat	N11170	0.6	0.6	0.6	0.6	1	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
B - 2004 Model Year		-	-	1	-	-	-	-	-	-	-	-	-
CORE, HEATER-REPLACE													
INC: Drain and Refill Coolant													
main unit above vin 176477	N11171	-	2.9	2.9	-	-	-	-	-	-	-	-	-
main unit 2003 model year and above	N11172	-	-	2.1	-	3.7	-	-	-	-	-	-	-

ADD:													
A - Recover/Recharge A/C System		-	0.7	0.7	-	0.7	-	-	-	-	-	-	-
aux unit/heat only	N11175	-	0.6	-	-	-	-	-	-	-	-	-	-
AUX A/C HEAT-REPLACE	N11176	0.5	0.5	0.5	0.5	0.8	-	-	-	-	-	-	-
POLICY: A													
INC: Drain and Refill Coolant													
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
CASE HALF, AUX A/C-REPLACE													
above vin 176477	N11177	-	0.8	0.8	-	0.8	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		-	0.7	0.7	-	0.7	-	-	-	-	-	-	-
BRACKET(S), COMPRESSOR MOUNTING-R&R OR REPLACE	N11173	0.8	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-
ADD:													
A - To Transfer Idler Pulley		0.2	0.2	0.2	0.2	-	-	-	-	-	-	-	-
CLUTCH PLATE AND HUB ASSEMBLY, COMPRESSOR-REPLACE (INCLUDES R&R COMPRESSOR)	N11180	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
COIL AND/OR HOUSING, COMPRESSOR CLUTCH-REPLACE	N11183	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
SEAL, SEAT AND/OR "O" RING, COMPRESSOR SHAFT-REPLACE (INCLUDES R&R COMPRESSOR)	N11186	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	-	-	-	-	-	-	-	-
COMPRESSOR ASSEMBLY-REPLACE	N11187	0.4	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-
ADD:													
A - Recover/Recharge A/C System		0.7	0.7	0.7	0.7	0.7	-	-	-	-	-	-	-
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	N11192	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-

A - W/Driveline Protection		0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
SOLENOID, STARTER MOTOR-REPLACE	P12026	1.6	1.6	1.6	1.4	-	-	-	-	-	-	-	-
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
DRIVE ASSEMBLY, STARTER MOTOR-REPLACE	P12027	1.6	1.6	1.6	1.5	-	-	-	-	-	-	-	-
INC: R&R starter motor.													
ADD:													
A - W/Driveline Protection		0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
BATTERY-CHARGE AND TEST (EACH)	P12030	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
BATTERY-REPLACE													
one	P12035	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-
both	P12037	0.4	0.4	0.4	-	0.4	-	-	-	-	-	-	-
CABLES, BATTERY-REPLACE													
positive													
battery to starter	P12040	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
ADD:													
A - 2006 Model Year		-	-	-	-	-	-	-	0.7	-	-	0.7	-
battery to battery	P12041	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
battery to winch	P12042	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
Negative													
battery to starter	P12043	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
battery to engine	P12044	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
battery to battery	P12045	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
battery to winch	P12046	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
HOLD DOWN, BATTERY-REPLACE	P12050	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
TRAY OR SUPPORT, BATTERY-REPLACE	P12055	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7
HORN ASSEMBLY-REPLACE	P12060	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
INC: One or Both.													
BRACKET, HORN, MOUNTING-REPLACE	P12067	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
HEADLAMP ASSEMBLY-REPLACE	P12070	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
HOUSING, HEADLAMP-REPLACE	P12071	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
SEALED BEAM OR RETAINING RING-REPLACE													
right	P12072	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
left	P12073	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
HEADLAMPS, ALIGN	P12074	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
BULBS/LAMPS, INTERNAL-REPLACE													
ash tray	P12075	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
visor vanity													
left	P12076	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
right	P12077	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
cargo	P12078	-	-	-	-	-	0.3	0.3	-	-	0.3	-	-
courtesy, front													
left	P12079	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
right	P12080	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2

courtesy, rear														
left	P12081	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3	
right	P12082	-	-	-	-	-	-	0.3	0.3	0.3	-	0.3	0.3	
BULBS/LAMPS, INTERNAL-REPLACE (Cont'd)														
dome														
front	P12085	-	-	-	-	-	0.2	0.2	0.2	-	0.2	-	0.2	
rear	P12086	-	-	-	-	-	-	0.2	0.2	-	-	-	0.2	
middle	P12087	-	-	-	-	-	-	-	0.3	-	-	0.3	-	
speedometer														
2004 model year & earlier	P12088	-	-	-	-	-	1.3	1.3	1.3	1.3	1.3	1.3	1.3	
2006 Model Year	P12100	-	-	-	-	-	-	-	0.3	-	-	0.3	-	
oil gauge	P12089	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	
volt gauge	P12090	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	
temp gauge	P12091	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	
fuel gauge	P12092	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	
ctis gauge	P12093	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	
clock	P12094	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	
Transmission temperature	P12095	-	-	-	-	0.3	-	-	-	-	-	-	-	
map light, front														
left	P12096	-	-	-	-	-	0.2	0.2	0.2	-	0.2	-	0.2	
right	P12097	-	-	-	-	-	0.2	0.2	0.2	-	0.2	-	0.2	
map light, rear														
left	P12098	-	-	-	-	-	-	0.2	0.2	-	-	-	0.2	
right	P12099	-	-	-	-	-	-	0.2	0.2	-	-	-	0.2	
shift indicator	P12102	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4	
INDICATOR LAMPS, DASH-REPLACE														
left turn	P12105	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-	
right turn	P12106	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-	
brake	P12107	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-	
seat belt	P12108	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-	
wait	P12109	0.3	0.3	0.3	-	0.3	-	-	-	-	-	-	-	
drain filter	P12110	0.3	0.3	0.3	-	0.3	-	-	-	-	-	-	-	
high beam	P12111	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-	
t-case lock	P12112	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-	
check engine	P12113	-	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	
transmission	P12114	-	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	
inflate	P12115	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	-	
check throttle	P12116	-	-	0.3	-	0.3	-	-	-	-	-	-	-	
STATUS CENTER	P12117	-	-	1.4	-	-	-	-	-	-	-	-	-	
BULBS/LAMPS, EXTERNAL-REPLACE														
park and turn signal														
left	P12121	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	
right	P12122	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	
roof clearance	P12123	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4	

[illegible]

cargo	P12160	-	-	-	-	-	0.2	0.2	-	-	0.2	-	-
dome	P12161	-	-	-	-	-	0.2	0.2	0.2	-	0.2	-	0.2
LENS, INDICATOR AND/OR BEZEL-REPLACE													
left turn/high beam	P12165	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	-
brake/seat belt	P12166	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	-
wait/drain filter	P12167	0.2	0.2	0.2	-	-	-	-	-	-	-	-	-
right turn/t-case link	P12168	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	-
check eng/trans	P12169	-	0.2	0.2	0.2	-	-	-	-	-	-	-	-
check engine/throttle warning	P12170	-	-	0.2	-	-	-	-	-	-	-	-	-
cti pump	P12171	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	-
GLOWPLUG indicator-REPLACE	P12175	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
INDICATOR, LOW COOLANT-REPLACE	P12176	-	0.3	0.3	-	-	-	-	-	-	-	-	-
MODULE, DAY-TIME RUN LIGHT-CANADIAN ONLY-REPLACE	P12177	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
MODULE, EXPRESS DOWN WINDOW-replace	p12178	-	-	-	-	-	-	0.5	0.5	-	0.5	0.5	-
MODULE, e Locker-REPLACE	p12179	-	-	-	-	-	-	-	0.4	-	-	0.4	-
MODULE, SEAT HEATER-REPLACE	p12181	-	-	-	-	-	-	-	0.2	-	-	0.2	-
ADD:													
A - 2004 and 2006 Model Years		-	-	-	-	-	-	-	1	-	-	1	-
COVER, FUSE BOX-REPLACE	P12180	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
FUSE-REPLACE	P12185	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
FUSE HOLDER, HTD. W/S-REPLACE	P12186	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	-
FLASHER-REPLACE													
hazard	P12190	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
turn	P12191	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
CIRCUIT BREAKER-REPLACE	P12195	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
RADIO/CASSETTE-REPLACE													
jvc/clarion	P12198	-	-	-	-	-	1.2	1.2	1.2	1.2	1.2	1.2	-
POLICY: A		-	-	-	-	-							-
amplifier	P12200	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	-
subwoofer	P12201	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	-
face, clarion	P12211	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	-
POLICY: A		-	-	-	-	-							-
delco	P12199	-	-	-	-	-	-	0.3	0.3	-	0.3	0.3	0.3
POLICY: A													
ADD:													
A - 2006 Model Year		-	-	-	-	-	-	-	0.3	-	-	0.3	-
amplifier	P12202	-	-	-	-	-	-	0.7	0.7	-	-	0.7	0.7
ADD:													
A - 2004 and 2006 Model Years		-	-	-	-	-	-	1.8	1.8	-	-	1.8	-
subwoofer assy	P12203	-	-	-	-	-	-	0.2	0.2	-	-	0.2	0.2
speaker, subwoofer, front	P12204	-	-	-	-	-	-	0.4	0.4	-	-	0.4	0.4
speaker, subwoofer, rear	P12210	-	-	-	-	-	-	0.4	0.4	-	-	0.4	0.4
speaker, subwoofer, front and rear	P12212	-	-	-	-	-	-	0.6	0.6	-	-	0.6	0.6
speaker, left center	P12213	-	-	-	-	-	-	0.7	0.7	-	-	0.4	0.7

	speaker, right center	P12218	-	-	-	-	-	-	0.7	0.7	-	-	0.4	0.7
	speaker, right and left center	P12219	-	-	-	-	-	-	0.9	0.9	-	-	0.5	0.9
SPEAKER, JVC/CLARION/DELCO-REPLACE														
	left front	P12205	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
	right front	P12206	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
	left rear	P12207	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4	0.4
	right rear	P12208	-	-	-	-	-	0.4	0.4	0.4	-	0.4	0.4	0.4
CD PLAYER-REPLACE														
POLICY: A														
	jvc/clarion	P12209	-	-	-	-	-	0.6	0.6	0.6	-	0.6	0.6	-
	delco 6 DISC	P12221	-	-	-	-	-	0.3	0.3	-	0.3	0.3	0.3	0.3
	delco 12 DISC	P12224	-	-	-	-	-	-	0.4	-	-	0.4	-	-
ANTENNA, RADIO-REPLACE														
	mast	P12214	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
	assembly	P12215	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
	cable	P12216	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
REAR SEAT AUDIO, REPLACE		P12223	-	-	-	-	-	0.2	0.2	-	-	-	-	0.2
SUPPRESSOR, NOISE, RADIO-REPLACE		P12217	-	-	-	-	-	1	1	1	1	1	1	1
LINK, FUSIBLE-REPLACE														
	battery	P12220	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
	alternator	P12222	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
	glowplug													
	left	P12225	0.4	0.4	0.4	-	-	-	-	-	-	-	-	-
	right	P12226	0.5	0.5	0.5	-	-	-	-	-	-	-	-	-
ALARM-REPLACE														
	multi-function	P12230	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	low air	P12231	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	overspeed	P12232	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
SWITCHES-REPLACE														
	back-up	P12236	-	-	-	-	-	1.2	1.2	1.2	1.2	1.2	1.2	1.2
	cargo/dome	P12237	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
ADD:														
A - 2004 & 2006 Model Years			-	-	-	-	-	-	1.3	1.3	-	1.3	1.3	-
	door lock													
	left	P12238	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
	right	P12239	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
	window													
	left front	P12240	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2	0.2
	right front	P12241	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2	0.2
	left rear	P12242	-	-	-	-	-	0.2	0.2	-	-	0.2	0.2	0.2
	right rear	P12243	-	-	-	-	-	0.2	0.2	-	-	0.2	0.2	0.2
	master	P12244	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2	0.2
	lock	P12245	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2	0.2
	door jamb													

left front	P12250	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
right front	P12251	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
left rear	P12252	-	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2
right rear	P12253	-	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2
SLANT	P12254	-	-	-	-	-	-	-	-	-	-	-	0.7
Vertical	P12269	-	-	-	-	-	-	-	0.7	-	-	-	-
oil pressure	P12255	-	-	-	-	-	1.3	1.3	1.3	1.3	1.3	1.3	1.3
2006 Model year	P12256	-	-	-	-	-	-	-	0.3	-	-	0.3	-
horn brush contact													
2004 model year and up	P12257	-	-	-	-	-	-	-	0.5	-	-	0.5	-
cold advance coolant temperature	P12260	0.2	0.2	-	-	-	-	-	-	-	-	-	-
fuel tank, auxiliary	P12261	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
ADD:													
A - 2004 & 2006 Model Years		-	-	-	-	-	-	1.3	1.3	-	1.3	1.3	-
headlamp i/p dimmer	P12262	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
ADD:													
A - 2004 & 2006 Model Years		-	-	-	-	-	-	1.3	1.3	-	1.3	1.3	-
ignition	P12263	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
park brake	P12264	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
stop light	P12265	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
turn signal and hazard	P12266	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
t-case indicator	P12267	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
wiper	P12268	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
ADD:													
A - 2004 & 2006 Model Years		-	-	-	-	-	-	1.3	1.3	-	1.3	1.3	-
intermittent wiper													
FRONT	P12270	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
REAR	P12281	-	-	-	-	-	-	-	-	-	-	-	0.2
ADD:													
A - 2004 & 2006 Model Years		-	-	-	-	-	-	1.3	1.3	-	1.3	1.3	-
ctis inflate/deflate	P12271	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
ctis selector	P12272	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
ambient temperature	P12274	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
transfer case range	P12275	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
neutral safety	P12276	-	-	-	-	-	1.2	1.2	1.2	1.2	1.2	1.2	1.2
power mirror	P12277	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
ADD:													
A - 2004 & 2006 Model Years		-	-	-	-	-	-	1.3	1.3	-	1.3	1.3	-
rear window defog.	P12278	-	-	-	-	-	0.2	0.2	-	-	0.2	-	0.2
heated windshield	P12279	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
cruise control	P12280	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
E LOCKER	P12282	-	-	-	-	-	-	-	0.2	-	-	0.2	-
SEAT HEATER	P12283	-	-	-	-	-	-	-	0.2	-	-	0.2	-
TOW HAUL	P12287	-	-	-	-	0.2	-	-	-	-	-	-	-

ARM, WIPER-REPLACE														
	left	P12325	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
	right	P12326	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
	both	P12327	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	rear	p12328	-	-	-	-	-	-	-	-	-	-	-	0.2
PIVOT ASSY, WIPER-REPLACE														
	left	P12329	-	-	-	-	-	1	1	1	1	1	1	1
	right	P12330	-	-	-	-	-	1	1	1	1	1	1	1
ADD:														
A - 2006 Model Year										0.6			0.6	
LINKAGE, WIPER-REPLACE														
	left	P12335	-	-	-	-	-	1.3	1.3	1.3	1.3	1.3	1.3	1.3
	right	P12336	-	-	-	-	-	1.3	1.3	1.3	1.3	1.3	1.3	1.3
ADD:														
A - 2006 Model Year										0.6			0.6	
HOSES, NOZZLES, W/S WASHER-REPLACE														
	rear	p12339	-	-	-	-	-	-	-	-	-	-	-	0.2
	left	P12340	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
	right	P12341	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
WINDSHIELD, PUMP ASSY, WASHER-REPLACE														
	front	P12342	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
	rear	p12346	-	-	-	-	-	-	-	-	-	-	-	0.5
RESERVOIR, WINDSHIELD WASHER FLUID-REPLACE														
1999 model year and above		P12343	-	-	0.6	-	0.6	-	-	-	-	-	-	-
PUMP ASSY, WINDSHIELD WASHER RESERVOIR-REPLACE														
1998 model year and below		P12344	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
SWITCH, LOW FLUID, WINDSHIELD WASHER RESERVOIR-REPLACE		P12345	-	-	0.2	-	0.5	-	-	-	-	-	-	-
ELEMENT AND/OR KNOB, CIGAR LIGHTER-REPLACE		P12350	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
CIGAR LIGHTER, ASSEMBLY-REPLACE		P12351	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
INSTRUMENT PANEL-REPLACE		P12355	-	-	-	-	-	2.2	2.2	2.2	2.2	2.2	2.2	2.2
SPEEDOMETER-REPLACE														
2000 model year and below		P12360	-	-	-	-	-	1.3	1.3	1.3	1.3	1.3	1.3	1.3
NOTE: See P12381 for 2001 Model Year and Above.														
ADAPTER, SPEEDOMETER, RATIO-REPLACE		P12361	-	0.4	0.4	0.4	-	-	-	-	-	-	-	-
CABLE, SPEEDOMETER 2000 MODEL YEAR AND BELOW-REPLACE		P12362	0.6	-	-	-	-	-	-	-	-	-	-	-
TACHOMETER 2000 MODEL YEAR AND BELOW-REPLACE		P12363	-	0.6	0.6	0.6	-	-	-	-	-	-	-	-
GAUGE, 2000 MODEL YEAR AND BELOW-REPLACE														
	temp	P12365	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	fuel	P12366	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	oil pressure	P12367	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	voltmeter	P12368	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	ctis	P12369	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
GAUGE MODULE, 2001 MODEL YEAR AND ABOVE-REPLACE														
	coolant/fuel	p12380	-	-	-	-	-	-	0.3	0.3	-	0.3	0.3	0.3

[illegible]

[illegible]

COMPASS MIRROR	P12454													
CTIS	P12455													
abs	P12460													
BOLTS, FASTENERS, FITTINGS (TIGHTEN)	P12465	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-

HUMMER H1							Accessories						
OPERATION DESCRIPTION	OPERATION NUMBER	ENGINE					MODEL						
		X	Y	Z/F	D/L	P	82	83 and 56	84 and 57	85	89 and 55	90 and 58	91 and 59
SOME LABOR OPERATIONS IN THIS SECTION HAVE AN ADD CONDITION "TO CLEAN PARTS ON VEHICLES OVER 30,000 MILES IF NEC." WHEN CLAIMING THIS "ADD," THE PARTICULAR LABOR OPERATION INVOLVED MUST BE CITED AS Y-TIME (ADD TIME).													
RUNNING BOARD-REPLACE													
left hand	R13000	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6	0.6
right hand	R13001	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6	0.6
BRACKET, RUNNING BOARD-REPLACE													
front													
left hand	R13005	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
right hand	R13006	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
rear													
left hand	R13007	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
right hand	R13008	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
CURVED TUBE, RUNNING BOARD-REPLACE													
left hand	R13009	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
right hand	R13010	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
END CAP, RUNNING BOARD-REPLACE													
left hand	R13015	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
right hand	R13016	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
WINCH ASSEMBLY-REPLACE	R13020	-	-	-	-	-	1.2	1.2	1.2	1.2	1.2	1.2	1.2
POLICY: A													
HAND CONTROLLER, WINCH-REPLACE	R13021	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
HOOK, WINCH CABLE-REPLACE	R13022	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
CABLE, WINCH-REPLACE	R13023	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
CONTROL PACK, WINCH-REPLACE	R13024	-	-	-	-	-	1.2	1.2	1.2	1.2	1.2	1.2	1.2
COVER, WINCH, CONTROL PACK-REPLACE	R13025	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
ELECTRIC MOTOR, WINCH-REPLACE	R13026	-	-	-	-	-	2.5	2.5	2.5	2.5	2.5	2.5	2.5
BRUSH SET, WINCH, ELECTRIC MOTOR-REPLACE	R13027	-	-	-	-	-	2.3	2.3	2.3	2.3	2.3	2.3	2.3
WINCH ASSEMBLY-RECONDITION	R13028	-	-	-	-	-	4.8	4.8	4.8	4.8	4.8	4.8	4.8
INC: R&R													
TRANSMITTER, KEYLESS ENTRY SYSTEM-REPLACE	R13030	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
KIT, LUGGAGE RACK-REPLACE													
POLICY: A													
3'	R13040	-	-	-	-	-	0.8	0.8	0.8	-	0.8	-	0.8
6'	R13041	-	-	-	-	-	-	1	1	-	-	-	1
9'	R13042	-	-	-	-	-	-	-	1.5	-	-	-	-

SIDE RAILS, LUGGAGE RACK-REPLACE														
	3'	R13050	-	-	-	-	-	0.3	0.3	0.3	-	0.3	-	0.3
	6'	R13051	-	-	-	-	-	-	0.5	0.5	-	-	-	0.5
	9'	R13052	-	-	-	-	-	-	-	0.7	-	-	-	-
END ASSEMBLY, LUGGAGE RACK-REPLACE		R13055	-	-	-	-	-	0.3	0.3	0.3	-	0.3	-	0.3
CROSS BARS, LUGGAGE RACK-REPLACE		R13060	-	-	-	-	-	0.3	0.3	0.3	-	0.3	-	0.3
FLOOR SECTION, LUGGAGE RACK-REPLACE														
	3'	R13065	-	-	-	-	-	0.3	0.3	0.3	-	0.3	-	0.3
	6'	R13066	-	-	-	-	-	-	0.8	0.8	-	-	-	0.8
	9'	R13067	-	-	-	-	-	-	-	1	-	-	-	-
END CAPS, LUGGAGE RACK-REPLACE														
	3'	R13070	-	-	-	-	-	0.3	0.3	0.3	-	0.3	-	0.3
	6'	R13071	-	-	-	-	-	-	0.5	0.5	-	-	-	0.5
	9'	R13072	-	-	-	-	-	-	-	0.8	-	-	-	-
CLAMP ASSEMBLY, LUGGAGE RACK-REPLACE		R13075	-	-	-	-	-	0.2	0.2	0.2	-	0.2	-	0.2
FLOOR MATS-REPLACE														
POLICY: A														
	front	R13077	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
	rear	R13080	-	-	-	-	-	-	0.2	0.2	0.2	-	0.2	0.2
WHEEL COVER, KIT-REPLACE		R13090	-	-	-	-	-	1.5	1.5	1.5	1.5	1.5	1.5	1.5
POLICY: A														
WHEEL COVER-REPLACE														
POLICY: A														
	one	R13091	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2	0.2
	two	R13092	-	-	-	-	-	0.4	0.4	0.4	0.4	0.4	0.4	0.4
	all	R13094	-	-	-	-	-	0.8	0.8	0.8	0.8	0.8	0.8	0.8
WHEEL COVER, MOUNTING BRACKET-REPLACE														
	one	R13096	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
	two	R13097	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6	0.6
	all	R13098	-	-	-	-	-	1.2	1.2	1.2	1.2	1.2	1.2	1.2
KIT, STATION WAGON, SOFT TOP-REPLACE		R13100	-	-	-	-	-	-	-	-	0.3	-	0.3	-
POLICY: A														
KIT, SLANT BACK-REPLACE		R13105	-	-	-	-	-	-	-	-	0.3	-	0.3	-
POLICY: A														
BOLTS, FASTENERS, FITTINGS (TIGHTEN)		R13110	0.3	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-

HUMMER H1							Service Bulletins						
OPERATION DESCRIPTION	OPERATION NUMBER	ENGINE					MODEL						
		X	Y	Z/F	D/L	P	82	83 and 56	84 and 57	85	89 and 55	90 and 58	91 and 59
SOME LABOR OPERATIONS IN THIS SECTION HAVE AN ADD CONDITION "TO CLEAN PARTS ON VEHICLES OVER 30,000 MILES IF NEC." WHEN CLAIMING THIS "ADD," THE PARTICULAR LABOR OPERATION INVOLVED MUST BE CITED AS Y-TIME (ADD TIME).													
label, epa noise-install	30101	0.3	0.3	0.3	0.3	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
kit, air induction system-install	31001	2.3	2.3	2.3	2.3	-	-	-	-	-	-	-	-
fuel line routing-replace	31002	0.6	-	-	-	-	-	-	-	-	-	-	-
shift linkage, transmission-replace	31301	0.5	-	-	-	-	-	-	-	-	-	-	-
extension, transfer lever-install	31302	0.8	0.8	0.8	0.8	-	-	-	-	-	-	-	-
POLICY: i													
clamp nut, geared hub-install													
w/ctis all 4 wheels	31601	6	6	6	6	-	-	-	-	-	-	-	-
w/o ctis all 4 wheels	31602	4.8	4.8	4.8	4.8	-	-	-	-	-	-	-	-
line, front geared hub vent-install	31603	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
parking brake, anti-rattle-install	31701	0.4	0.4	0.4	0.4	-	-	-	-	-	-	-	-
washer, wheel center w/ctis (per tire)-install	31805	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
washer, wheel, center w/o ctis (per tire)-install	31806	1	1	1	1	-	-	-	-	-	-	-	-
washer for spare tire, wheel center-install	31807	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-
hood squeaks-adjust	32201	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
kit, b-beam modification (1992/1993)-MODIFY	32202	-	-	-	-	-	7.8	7.8	7.8	7.8	-	-	-
KIT, FRONT SEAT MODIFICATION (1992/1993)-modify	32203	-	-	-	-	-	1.3	1.3	1.3	1.3	-	-	-
seat belt, passenger's-install	32204	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
kit, two-door power door lock													
Register Sale on DCS	32206	-	-	-	-	-	0.1	0.1	0.1	-	-	-	-
kit, four door power door lock													
Register Sale on DCS	32207	-	-	-	-	-	-	0.1	0.1	-	-	-	-
glove box for a/c kit-install	32208	-	-	-	-	-	1.4	1.4	1.4	1.4	1.4	1.4	-
POLICY: i													
kit, soft-top enhancement (1992/1993)-install	32209	-	-	-	-	-	-	-	-	4	-	4	-
kit, soft top-install	32210	-	-	-	-	-	-	-	-	1	-	1	-
kit, tonneau cover-install	32211	-	-	-	-	-	0.3	0.3	-	0.3	0.3	0.3	-
kit, station wagon soft-top													
Register Sale on DCS	32212	-	-	-	-	-	-	-	0.1	-	-	-	-

Kit, slant back soft-top														
Register Sale on DCS	32213	-	-	-	-	-	-	-	-	-	0.1	-	0.1	-
kit, remote entry system														
Register Sale on DCS	32214	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	-
kit, driver's seat armrest-install	32215	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6	0.6	-
window weatherstrip-modify	32217	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	-
kit, lamp reel														
Register Sale on DCS	32401	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	-
BRACKET MOUNTING, GENERATOR LOWER	32501	-	-	-	-	-	8.4	8.4	8.4	8.4	8.4	8.4	8.4	-
SUPPORT-REPLACE														
KIT, BED-MOUNTED SPARE TIRE CARRIER ACCESSORY														
Register Sale on DCS	32902	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	-
KIT, SWING-AWAY SPARE TIRE CARRIER														
Register Sale on DCS	32903	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
KIT, DRIVELINE PROTECTION, W/WINCH														
Register Sale on DCS	32904						0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
KIT, TRAILER TOWING WIRING-INSTALL	32907	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5	-
KIT, 12,000-POUND CAPACITY WINCH														
Register Sale on DCS	32908	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
KIT, PIONEER TOOL STOWAGE														
Register Sale on DCS	32909	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
KIT, WINCH CONTROL BOARD-INSTALL	32910	-	-	-	-	-	2.4	2.4	2.4	2.4	2.4	2.4	2.4	-
KIT, DRIVELINE PROTECTION, W/O WINCH														
Register Sale on DCS	32911	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
AIR CONDITIONING OUTPUT ADJUSTMENT-ADJUST	32913	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
KIT, AUXILIARY AIR CONDITIONING AND HEATING (1992/1993)														
POLICY: I														
Register Sale on DCS	32914	0.1	0.1	-	-	-	-	-	-	-	-	-	-	-
KIT, CTIS SELECTOR SWITCH KNOB AND DECAL-INSTALL	32916	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7	-
POLICY: I														
KIT, SIX-FOOT ROOF RACK														
Register Sale on DCS	32917	-	-	-	-	-	0.1	0.1	0.1	-	0.1	-	0.1	-
KIT, NINE-FOOT ROOF RACK														
Register Sale on DCS	32918	-	-	-	-	-	-	-	0.1	-	-	-	-	-
FUEL TUBE/HARNESS RELOCATION (1992/1993)-MODIFY	41001	1.7	1.7	-	-	-	-	-	-	-	-	-	-	-
POLICY: J														
TIRE AND RUNFLAT CLEANING-SERVICE	41801	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
WHEEL RUNOUT INSPECTION-INSPECT	41802	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
CTIS (ELECTRICAL)-TEST	41806	0.6	0.6	0.6	0.6	-	-	-	-	-	-	-	-	-
CTIS (AIR LEAK)-TEST	41807	2.6	2.6	0.5	0.5	-	-	-	-	-	-	-	-	-
REGULATOR, ROLL-UP WINDOW GLASS-REPLACE	42201	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6
KIT, GENERATOR CONVERSION 85 TO 124 AMP-INSTALL	42501	1.2	1.2	1.2	1.2	-	-	-	-	-	-	-	-	-
SEAL, CONNECTOR (1992/1993/1994)-INSPECT	42602	0.4	0.4	-	-	-	-	-	-	-	-	-	-	-
POLICY: J														

SEAL AND SWITCH, CONNECTOR (1992/1993/1994)-REPLACE	42603	1.6	1.6	-	-	-	-	-	-	-	-	-	-	-
POLICY: J														
TRAILER WIRING MODIFICATION-MODIFY	42801	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
KIT, POWER MIRROR														
Register Sale on DCS	42906	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
KIT, TWO-DOOR POWER WINDOW														
Register Sale on DCS	42907	-	-	-	-	-	0.1	-	-	-	0.1	-	-	-
KIT, RUNNING BOARD														
Register Sale on DCS	42908	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
KIT, AIR CONDITIONING COMPRESSOR MOUNTING REINFORCEMENT (1992/1993)-INSTALL	42909	1.3	1.3	1.3	1.3	-	-	-	-	-	-	-	-	-
POLICY: I														
KIT, THREE-FOOT ROOF RACK														
Register Sale on DCS	42910	-	-	-	-	-	0.1	0.1	0.1	-	0.1	-	0.1	-
KIT, RUNNING BOARD W/DRIVELINE PROTECTION														
Register Sale on DCS	42911	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
KIT, AUXILIARY AIR CONDITIONING AND HEATING (1994/1995)														
POLICY: I														
Register Sale on DCS	42914	0.1	0.1	-	-	-	-	-	-	-	-	-	-	-
KIT, FOUR-DOOR POWER WINDOW														
Register Sale on DCS	42917	-	-	-	-	-	-	0.1	0.1	-	-	-	0.1	-
KIT, AIR CONDITIONING AMBIENT TEMPERATURE SWITCH (1994)-INSTALL	42918	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-	-
KIT, HVAC ENHANCEMENT (1994)-INSTALL	42920	12.2	12.2	-	-	-	-	-	-	-	-	-	-	-
POLICY: I														
TACHOMETER (1994-UP)-INSTALL	50201	0.9	0.9	0.9	0.9	-	-	-	-	-	-	-	-	-
CABLE, W.O.T. ACCELERATOR-INSPECT/ADJUST	50202	0.5	0.5	-	0.5	-	-	-	-	-	-	-	-	-
BELT, DUAL GROOVE PULLEY (1992/1993)-INSTALL	50303	0.8	0.8	-	-	-	-	-	-	-	-	-	-	-
FUEL TANK VENT (GASOLINE)-INSTALL	50306	-	-	-	0.9	-	-	-	-	-	-	-	-	-
POLICY: I														
KIT, FRONT GEARED HUB VENT LINE-INSTALL	50601	0.5	5	5	0.5	-	-	-	-	-	-	-	-	-
POLICY: J														
STEERING LINKAGE COMPONENTS-INSTALL	50801	2.4	2.4	2.4	2.4	-	-	-	-	-	-	-	-	-
POLICY: A														
BALL JOINTS, UPPER CONTROL ARM-INSTALL	50802	5.2	5.2	5.2	5.2	-	-	-	-	-	-	-	-	-
POLICY: A														
KIT, HOOD LOCK														
Register Sale on DCS	51001	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	-
RATTLE OR SQUEAK IN B-PILLAR-REPAIR	51003	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	-
POCKET, LOAD BARRIER STORAGE-INSTALL	51006	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	0.3
WATER LEAK, PERIMETER WINDSHIELD-REPAIR	51007	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	0.7	-
WATER LEAK, WINDSHIELD LOWER RETAINER-REPAIR	51010	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	-
GUARD, DOOR STRIKER-INSTALL	51011	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3	-

[illegible]

clip, anti-rattle, transfer case shift lever-install	80501	-	0.3	0.3	-	-	-	-	-	-	-	-	-
ADD:													
A - 1992-1995		0.5	0.5	-	0.5	-	-	-	-	-	-	-	-
loss of 4th gear, slipping in 4th gear, busy 3-4 shifting or torque converter clutch (tcc) cycling (1996 and 1997)	80502	2	2	2	2	-	-	-	-	-	-	-	-
POLICY: A													
amg r9801-transfer case access plug (1996 & 1997 vins 173698 through 178046)													
inspect and replace plug	80503	0.3	0.3	0.3	0.3	-	-	-	-	-	-	-	-
inspect and replace transfer case	80504	3.5	3.5	3.5	3.5	-	-	-	-	-	-	-	-
POLICY: A													
kit, seat side retainer	81001	-	-	-	-	-	-	0.3	0.3	-	0.3	-	-
kit, ventilation	81002	-	-	-	-	-	0.1	0.1	0.1	-	0.1	-	-
soft top "c" pillar cover retainer loose or disconnected (1998 vin 181242 and below)	81005	-	-	-	-	-	-	-	-	-	-	0.6	-
main hvac unit servicing (1995, 1996, 1997)	81104	-	10	10	-	-	-	-	-	-	-	-	-
POLICY: A													
ADD:		-	-	-	-	-	-	-	-	-	-	-	-
A - 1995 and 1996 VIN D vehicles		-	-	-	1	-	-	-	-	-	-	-	-
B - 1994 VIN R vehicles		-	1.5	-	-	-	-	-	-	-	-	-	-
heavy duty turn signal flasher (before VIN 179962)	81201	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	-
RADIO INOPERATIVE (VIN 176477 AND UP WITH DELCO OR MONSOON RADIO)													
REMOVE AND INSTALL FUSE	81202	-	-	-	-	-	-	0.2	0.2	-	0.2	0.2	-
REPLACE RADIO	12199	-	-	-	-	-	-	0.3	0.3	-	0.3	0.3	-
kit, dual oil filter													
Register Sale on DCS	81301	0.1	0.1	0.1	-	-	-	-	-	-	-	-	-
kit, hourmeter													
Register Sale on DCS	81302	0.1	0.1	0.1	-	-	-	-	-	-	-	-	-
kit, delco cd changer (vin 176477-above)													
Register Sale on DCS	81303	-	0.1	0.1	-	-	-	-	-	-	-	-	-
kit, air filter restriction													
Register Sale on DCS	81304	0.1	0.1	0.1	-	-	-	-	-	-	-	-	-
KIT, OFF ROAD ACCESSORY													
Register Sale on DCS	81307	-	-	-	-	-	-	-	0.1	-	-	-	-
KIT, SEAT HEATER													
Register Sale on DCS	81308	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
DELCO AUDIO SYSTEM REMOTE (VIN 176477 AND NEWER VEHICLES)	81309	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
UPHOLSTERY, LEATHER (SEAT COVERS)													
Register Sale on DCS	81310	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
ROLLER FAIRLEAD													
Register Sale on DCS	81312	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1

kit, dash trim appliqué														
Register Sale on DCS	81313	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
upholstery, leather auxiliary seat cover (1994 and newer)		-	-	-	-	-	-	0.75	0.75	0.75	0.75	0.75	0.75	0.75
Register Sale on DCS	81314	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
kit, traveler														
Register Sale on DCS	81315	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
kit, external tire repair accessory														
Register Sale on DCS	81316	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
kit, winch accessory														
Register Sale on DCS	81318	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
no start, stall	90301													
	use	-	-	3	-	-	-	-	-	-	-	-	-	-
	C3347													
trans default second gear	90501	-	0.4	0.4	0.4	-	-	-	-	-	-	-	-	-
master cylinder mount hardware	90701	-	-	-	-	-	-	-	0.8	0.8	-	0.8	0.8	-
Reversed polarity														
Checking	91201	-	-	-	-	-	-	-	0.2	0.2	-	0.2	0.2	-
repair	91202	-	-	-	-	-	-	-	0.7	0.7	-	0.7	0.7	-
Harness, Vertical door delay lock														
repair	91204	-	-	-	-	-	-	-	-	1.5	-	-	-	-
Checking	91208	-	-	-	-	-	-	-	-	0.2	-	-	-	-
Kit, fuse box decal														
repair	91205	-	-	0.2	-	-	-	-	-	-	-	-	-	-
Checking	91206	-	-	0.2	-	-	-	-	-	-	-	-	-	-
Kit, bedliner														
Register Sale on DCS	91301	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1	0.1
Kit, side step bars														
Register Sale on DCS	91302	-	-	-	-	-	-	-	0.1	0.1	0.1	-	0.1	0.1
Kit, bike rack														
Register Sale on DCS	91303	-	-	-	-	-	-	0.1	0.1	0.1	-	0.1	-	0.1
Kit, side load roof rack														
Register Sale on DCS	91304	-	-	-	-	-	-	0.1	0.1	0.1	-	0.1	-	0.1
Kit, ss front grille cover														
Register Sale on DCS	91306	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
Kit, ss rocker panel protection cover														
Register Sale on DCS	91307	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
Kit, floor mat														
Register Sale on DCS	91309	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
Kit, ss front bumper cover w/o winch														
Register Sale on DCS	91310	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
Kit, ss front bumper cover w/ winch														
Register Sale on DCS	91311	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
Kit, ss skid plate cover w/o winch														
Register Sale on DCS	91312	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1

[illegible]

	Register Sale on DCS	91334	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
flexible brake line recall		701	-	-	-	-	-	0.7	0.7	0.7	0.7	0.7	0.7	-
geared hub seals		901	1	1	1	1	-	-	-	-	-	-	-	-
whistling noise in hvac-flow cntrl valve		1104	-	-	-	-	-	-	0.5	0.5	-	0.5	0.5	0.5
power window lockout switch-replace		1203	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5	0.5
heated windshield switch and Mtg plate		1204	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3
kit, aluminum roof rack														
	Register Sale on DCS	1301	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	-	0.
kit, light bar														
	Register Sale on DCS	1303	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
kit, steel rocker panel protection														
	Register Sale on DCS	1306	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
kit, aluminum rocker panel protection														
	Register Sale on DCS	1307	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
kit, stainless steel accessory recessed wheel cover (round holes)														
	Register Sale on DCS	1308	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
accessory black rubber floor mats														
	Register Sale on DCS	1309	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
kit, trailer tow														
	Register Sale on DCS	1310	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
kit, delco 6-disc cd changer														
	Register Sale on DCS	1311	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
kit, off-road accessory														
	Register Sale on DCS	1313	-	-	-	-	-	-	0.1	-	-	-	0.1	-
kit, center console knee panel														
	Register Sale on DCS	1317	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
kit, remote garage door interface														
	Register Sale on DCS	1318	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
kit, deluxe outside power mirror														
	Register Sale on DCS	1319	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
momentary increase in engine idle speed														
Calibrate PCM		C3377	-	-	0.5	-	-	-	-	-	-	-	-	-
Non-GM Sublet Allowance		10201	-	-	0.5	-	-	-	-	-	-	-	-	-
water-in-fuel swiTCh		C3150	0.5	0.5	0.5	-	-	-	-	-	-	-	-	-
ADD:														
A - Above VIN 182961			-	-	0.1	-	-	-	-	-	-	-	-	-
customer satisfaction campaign		10501	-	-	-	-	-	-	3	3	-	3	3	3
amg r0101-transfer case cooler														
ctis hose strain relief		10601	-	-	-	-	-	-	0.6	0.6	0.6	0.6	0.6	0.6
ALUMINUM WHEEL LUG COVER TOOL		10602	-	-	-	-	-	-	0.2	0.2	0.2	0.2	0.2	0.2
product recall amg r0102-turn signal switch		10801	-	-	-	-	-	-	0.5	0.5	0.5	0.5	0.5	0.5
geared hub input and output seals		10902	-	-	-	-	-	1	1	1	1	1	1	1
door armrests		11001	-	-	-	-	-	0.3	0.3	0.3	0.3	0.3	0.3	0.3

reel lamp														
Register Sale on DCS	11301	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
17" aluminum one-piece wheel/tire assy.														
Register Sale on DCS	11302	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
kit, rear bumper closeout panel														
Register Sale on DCS	11303	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
universal electronic holder														
Register Sale on DCS	11304	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
KIT, BRUSHGUARD (STANDARD)														
Register Sale on DCS	11305	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
NOTE: See operation number K9230 on page 10-15 for labor times.														
KIT, WINCH														
Register Sale on DCS	11306	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
NOTE: See Operation Number R13020 on page 13-1 for labor times.														
KIT, AUXILIARY SEAT														
Register Sale on DCS	11307	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	-
NOTE: See operation numbers M10340 and M10345 on page 10-9 for labor times.														
ACCESSORY REAR SEAT ARMREST														
Register Sale on DCS	11308	-	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
kit, dash trim applique (2001 & 2002)														
Register Sale on DCS	11311	-	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1
cargo area liner														
Register Sale on DCS	11314	-	-	-	-	-	-	-	-	0.1	-	-	-	-
kit, door latch limiter														
Register Sale on DCS	11316	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
high intensity discharge spread beam lights														
Register Sale on DCS	21301	-	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1
quartz halogen accessory lights														
Register Sale on DCS	21302	-	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1
accessory fender flares														
Register Sale on DCS	21303	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
NOTE: For vehicles with Rocker Panel Protection.														
center tunnel rack														
Register Sale on DCS	21305	-	-	-	-	-	-	-	0.1	0.1	0.1	-	0.1	0.1
KIT, LEATHER ARMREST COVER														
Register Sale on DCS	21306	-	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1
kit, aluminum wheel spare tire carrier adapter														
Register Sale on DCS	21308	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
REAR BUMPER CENTER CLOSEOUT PANEL														
Register Sale on DCS	21310	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
Wheel house rack														
Register Sale on DCS	21311	-	-	-	-	-	-	-	-	0.1	-	-	-	-

[illegible]

turn signal mirror kit	Register Sale on DCS	41307	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
VEHICLE COVER	Register Sale on DCS	41308	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
hummer side reflector chrome trim bezel kit	Register Sale on DCS	41309	-	-	-	-	-	-	-	0.1	-	-	-	-
SS BEZEL AND INSERT FOR MAIN FUEL TANK FILLER APPLIQUE	Register Sale on DCS	41310	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
HUMMER OFF-ROAD JACK KIT	Register Sale on DCS	41311	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
TRIPLE BALL WITH SHACKLE HITCH	Register Sale on DCS	41312	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
TROPICOOOL FRESH BAG	Register Sale on DCS	41314	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
TIRE UTILITY STEP	Register Sale on DCS	41315	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
CUSTOM STEERING WHEEL KITS	Register Sale on DCS	41316	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
SIDE STEP BARS	Register Sale on DCS	41317	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
hummer removable rear mud flap kit	Register Sale on DCS	41319	-	-	-	-	-	-	0.1	0.1	0.1	-	0.1	-
ELECTRONIC FLARES	Register Sale on DCS	41320	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
protective seat cover kit	Register Sale on DCS	41324	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
textured aluminum roof rack	Register Sale on DCS	41325	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
stainless steel tail light bezel applique kit	Register Sale on DCS	41327	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	-	0.1
leather auxilliary seat upholstery kit	Register Sale on DCS	41329	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
stainless steel rear marker lights trim applique kit	Register Sale on DCS	41330	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
tire utility step	Register Sale on DCS	41331	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
cargo area liner kit (2004 & 2006)	Register Sale on DCS	41333	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
rubber floor mat sets	Register Sale on DCS	51301	-	-	-	-	-	-	-	0.1	-	-	0.1	-
cargo area liner kit (2004 & 2006)	Register Sale on DCS	51302	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
rubber floor mats w/carpet inserts	Register Sale on DCS	51303	-	-	-	-	-	-	-	0.1	-	-	0.1	-

[illegible]

(2001 & 2002)															
	Register Sale on DCS	51331	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1	0.1
turn signal mirror kit (2001-2006)															
	Register Sale on DCS	51332	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1	0.1
center tunnel rack organizer															
	Register Sale on DCS	51337	-	-	-	-	-	-	0.1	0.1	-	0.1	0.1	0.1	0.1
pintle hitch with 2" or 2 5/16" ball															
	Register Sale on DCS	51338	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
skyfi 2 xm pro kit															
	Register Sale on DCS	61301	-	-	-	-	-	-	0.1	0.1	-	0.1	-	0.1	0.1
fender rack organizer															
	Register Sale on DCS	61302	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
fender rack saddlebag															
	Register Sale on DCS	61304	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
dual voltage refrigerator/freezer															
	Register Sale on DCS	61310	-	-	-	-	-	-	-	0.1	-	-	-	-	-
Body paint protection kit (2001 and later)															
	Register Sale on DCS	61311	-	-	-	-	-	-	0.1	0.1	-	-	-	-	-
accessory floor mats															
	Register Sale on DCS	61312	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
high intensity discharge spread beam lights															
	Register Sale on DCS	61313	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
winch fairlead mounted license plate holder kit															
	Register Sale on DCS	61314	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
carpeted floor mat sets (2003 & earlier)															
	Register Sale on DCS	61315	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
nightdriver mounting bracket (2004 & 2006)															
	Register Sale on DCS	61318	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
first aid kit															
	Register Sale on DCS	61319	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
aluminum case flashlights															
	Register Sale on DCS	61321	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
side step bars															
	Register Sale on DCS	71304	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
rear winch kit															
	Register Sale on DCS	71306	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
soft spare tire cover															
	Register Sale on DCS	71308	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1	0.1
Frame Rail protectors															
	Register Sale on DCS	71311	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
bluetooth phone adapter kit															
	Register Sale on DCS	71312	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
roof rack net															

Register Sale on DCS	71314	-	-	-	-	-	0.1	0.1	0.1	-	0.1	-	0.1
Fully Rotating Pintle Hitch													
Register Sale on DCS	71315	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1
aluminum 17" two piece wheels with machined windows													
Register Sale on DCS	71316	-	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1
eclipse radio with hitch camera													
Register Sale on DCS	71319	-	-	-	-	-	-	-	0.1	-	-	0.1	-
17" beadlock for 17" two-piece wheels													
Register Sale on DCS	71325	-	-	-	-	-	0.1	0.1	0.1	0.1	0.1	0.1	0.1